

FORM
6
Rev
02/11

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80205 Phone: (303) 894-2100 Fax: (303) 894-2109



DE	ET	OE	ES
----	----	----	----

Date Received:

09/26/2017

Document Number:

Doc# 2227621

WELL ABANDONMENT REPORT

This form is to be submitted as an Intent to Abandon whenever an abandonment is planned on a borehole. After the abandonment is complete, this form shall again be submitted as a Subsequent Report of the actual work completed. The approved intent shall be valid for six months after the approval date, after that period, a new intent will be required. Attachments required with the Intent to Abandon are wellbore diagrams of the current configuration and the proposed configuration with plugs set.

A Subsequent Report of Abandonment shall indicate the actual work completed. Attachments required with a Subsequent Report are a wellbore diagram showing plugs that were set and casing remaining in the hole, the job summaries from all plugging contractors used, including wireline and cementing (third party verification) and any logs that may have been run during abandonment.

OGCC Operator Number: 80530 Contact Name: David Cook
 Name of Operator: Devon Energy FBO Snyder Oil Corp. Phone: (405) 552-7848
 Address: 333 West Sheridan Avenue Fax: _____
 City: Oklahoma City State: OK Zip: 73102 Email: david.cook@dnv.com
 For Intent 24 hour notice required, Name: Craig Burger Tel: (970) 625-2497
 COGCC contact: Email: craig.burger@state.co.us

API Number 05-045-06388--
 Well Name: Snyder-Barton Porter Well Number: #2-21
 Location: QtrQtr: NWNW Section: 21 Township: 6S Range: 90W Meridian: _____
 County: Garfield Federal, Indian or State Lease Number: FEE
 Field Name: Wildcat Field Number: 99999

Notice of Intent to Abandon Subsequent Report of Abandonment

Only Complete the Following Background Information for Intent to Abandon

Latitude: 39.520661 Longitude: -107.454417
 GPS Data:
 Data of Measurement: _____ PDOP Reading: _____ GPS Instrument Operator's Name: _____
 Reason for Abandonment: Dry Production for Sub-economic Mechanical Problems
 Other Unknown
 Casing to be pulled: Yes No Estimated Depth: 578'
 Fish in Hole: Yes No If yes, explain details below
 Wellbore has Uncemented Casing leaks: Yes No If yes, explain details below
 Details: _____

Current and Previously Abandoned Zones

Formation	Code	Perf. Top	Perf. Btm	Date	Method of Isolation	Plug Depth

Total: 0 zone(s)

Casing History

Casing Type	Size of Hole	Size of Casing	Weight Per Foot	Setting Depth	Sacks Cement	Cement Bot	Cement Top	Status

Plugging Procedure for Intent and Subsequent Report

CIBP #1: Depth _____ with _____ sacks cmt on top. CIPB #2: Depth _____ with _____ sacks cmt on top.
 CIBP #3: Depth _____ with _____ sacks cmt on top. CIPB #4: Depth _____ with _____ sacks cmt on top.
 CIBP #5: Depth _____ with _____ sacks cmt on top.

NOTE: Two(2) sacks cement required on all CIBPs.

Set 185 sks cmt from 578 ft. to 0 ft. in Plug Type: Cement CI G Plug Tagged:
 Set _____ sks cmt from _____ ft. to _____ ft. in Plug Type: _____ Plug Tagged:
 Set _____ sks cmt from _____ ft. to _____ ft. in Plug Type: _____ Plug Tagged:
 Set _____ sks cmt from _____ ft. to _____ ft. in Plug Type: _____ Plug Tagged:
 Set _____ sks cmt from _____ ft. to _____ ft. in Plug Type: _____ Plug Tagged:

Perforate and squeeze at _____ ft. with _____ sacks. Leave at least 100 ft. in casing _____ CICR Depth
 Perforate and squeeze at _____ ft. with _____ sacks. Leave at least 100 ft. in casing _____ CICR Depth
 Perforate and squeeze at _____ ft. with _____ sacks. Leave at least 100 ft. in casing _____ CICR Depth
(Cast Iron Cement Retainer Depth)

Set _____ sacks half in. half out surface casing from _____ ft. to _____ ft. Plug Tagged:
 Set _____ sacks at surface
 Cut four feet below ground level, weld on plate Above Ground Dry-Hole Marker: Yes No
 Set _____ sacks in rat hole Set _____ sacks in mouse hole

Additional Plugging Information for Subsequent Report Only


Casing Recovered: _____ ft. of _____ inch casing Plugging Date: _____
 *Wireline Contractor: _____ *Cementing Contractor: _____

Type of Cement and Additives Used: _____

Flowline/Pipeline has been abandoned per Rule 1103 Yes No *ATTACH JOB SUMMARY

Provide Technical Detail:

I hereby certify all statements made in this form are, to the best of my knowledge, true, correct, and complete.

Signed:  Print Name: David Cook
 Title: Regulatory Specialist Date: 09/26/2017 Email: david.cook@dvn.com

Based on the information provided herein, this Well Abandonment Report (Form 6) complies with COGCC Rules and applicable orders and is hereby approved.

COGCC Approved: _____ Date: _____

CONDITIONS OF APPROVAL, IF ANY:

Attachment Check List

Att Doc Num	Name
1	P&A Procedure

Total Attach: _____

General Comments

<u>User Group</u>	<u>Comment</u>	<u>Comment Date</u>

Total:

See attached Plug & Abandonment Procedure.

Note: Cement to be used is Class G; 5 gallons of water per sack to 15.6 lbs/gal.
producing 1.15 Cu. Ft/sx.