

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

401415310

Date Received:

09/28/2017

Spill report taken by:

GINTAUTAS, PETER

Spill/Release Point ID:

452278

SPILL/RELEASE REPORT (SUPPLEMENTAL)

This form is to be submitted by the party responsible for the oil and gas spill or release. Refer to COGCC Rule 906.b. for reporting requirements of spills or releases of E&P Waste or produced fluids. Submit a Site Investigation and Remediation Workplan (Form 27) when requested by the Director.

OPERATOR INFORMATION

Name of Operator: <u>KERR MCGEE OIL & GAS ONSHORE LP</u>	Operator No: <u>47120</u>	Phone Numbers
Address: <u>P O BOX 173779</u>		Phone: <u>(720) 9294306</u>
City: <u>DENVER</u> State: <u>CO</u> Zip: <u>80217-3779</u>		Mobile: <u>()</u>
Contact Person: <u>Erik Mickelson</u>		Email: <u>Erik.Mickelson@anadarko.com</u>

INITIAL SPILL/RELEASE REPORT

Initial Spill/Release Report Doc# 401408362

Initial Report Date: 09/20/2017 Date of Discovery: 09/20/2017 Spill Type: Historical Release

Spill/Release Point Location:

Location of Spill/Release: QTRQTR NWNW SEC 25 TWP 3N RNG 67W MERIDIAN 6

Latitude: 40.201320 Longitude: -104.847968

Municipality (if within municipal boundaries): _____ County: WELD

Reference Location:

Facility Type: TANK BATTERY Facility/Location ID No _____

No Existing Facility or Location ID No.

Well API No. (Only if the reference facility is well) 05- _____

Fluid(s) Spilled/Released (please answer Yes/No):

Was one (1) barrel or more spilled outside of berms or secondary containment? Yes

Secondary containment, including walls & floor regardless of construction material, must be sufficiently impervious to contain any discharge from primary containment until cleanup occurs.

Were Five (5) barrels or more spilled? No

Estimated Total Spill Volume: use same ranges as others for values

Estimated Oil Spill Volume(bbl): Unknown Estimated Condensate Spill Volume(bbl): 0

Estimated Flow Back Fluid Spill Volume(bbl): 0 Estimated Produced Water Spill Volume(bbl): Unknown

Estimated Other E&P Waste Spill Volume(bbl): 0 Estimated Drilling Fluid Spill Volume(bbl): 0

Specify: _____

Land Use:

Current Land Use: NON-CROP LAND Other(Specify): _____

Weather Condition: Sunny, 85 degrees F

Surface Owner: FEE Other(Specify): _____

Check if impacted or threatened by spill/Release (please answer Yes/No to all that apply):

Waters of the State Residence/Occupied Structure Livestock Public Byway Surface Water Supply Area

As defined in COGCC 100-Series Rules

Describe what is known about the spill/release event (what happened -- including how it was stopped, contained, and recovered):

On September 19, 2017, environmental testing activities associated with a produced water sump closure was conducted at the Erickson Birkle P25-4JI Tank Battery location. Shallow groundwater was encountered at two feet bgs in the sump's excavation. Four sidewall soil samples and one groundwater sample were collected and submitted for laboratory analysis. Soil samples were analyzed for BTEX, TPH - GRO by Method 8260, and TPH - DRO and RRO by Method 8015. The groundwater sample was analyzed for BTEX by Method 8260. The groundwater results were received on September 20 indicating benzene levels at 5.92 ug/L exceeding Table 910-1 allowable groundwater concentrations. All four soil samples were submitted to the laboratory and the sample with the highest PID reading was analyzed. The laboratory analytical results for soil sample (N01@1.5') were ND for all constituents. Based on the groundwater results, the remaining three soil samples will be analyzed.

List Agencies and Other Parties Notified:

OTHER NOTIFICATIONS

Date	Agency/Party	Contact	Phone	Response
9/20/2017	Weld County	Roy Rudisill	--email	
9/20/2017	Weld County	Troy Swain	--email	
9/20/2017	Weld County	Tom Parko	--email	
9/20/2017	Landowner	Landowner	--phone call	

SPILL/RELEASE DETAIL REPORTS

#1 Supplemental Report Date: 09/28/2017

FLUIDS	BBL's SPILLED	BBL's RECOVERED	Unknown
OIL	_____	_____	<input checked="" type="checkbox"/>
CONDENSATE	_____	<u>0</u>	<input type="checkbox"/>
PRODUCED WATER	_____	_____	<input checked="" type="checkbox"/>
DRILLING FLUID	_____	<u>0</u>	<input type="checkbox"/>
FLOW BACK FLUID	_____	<u>0</u>	<input type="checkbox"/>
OTHER E&P WASTE	_____	<u>0</u>	<input type="checkbox"/>

specify: _____

Was spill/release completely contained within berms or secondary containment? NO Was an Emergency Pit constructed? NO

Secondary containment, including walls & floor regardless of construction material, must be sufficiently impervious to contain any discharge from primary containment until cleanup occurs.

A Form 15 Pit Report shall be submitted within 30 calendar days after the construction of an emergency pit

Impacted Media (Check all that apply) Soil Groundwater Surface Water Dry Drainage Feature

Surface Area Impacted: Length of Impact (feet): 14 Width of Impact (feet): 11

Depth of Impact (feet BGS): 2 Depth of Impact (inches BGS): 24

How was extent determined?

On September 19, 2017, four confirmation sidewall soil samples (N01@1.5', E01@1.5', S01@1.5', and W01@1.5') were collected from the excavation for laboratory analysis of TPH, BTEX, pH, and EC. Concentrations of all confirmation sidewall soil sample analyzed constituents were either not detectable at the lab's detection limit or below COGCC Table 910-1 allowable concentrations. Both pH and EC were within COGCC allowable thresholds. Groundwater was encountered in the excavation at two feet below ground surface and one sample was collected for laboratory analysis of BTEX. The laborator results indicated benzene exceeded COGCC Table 910-1 allowable concentrations at 5.92 ug/L. Toluene, ethylbenzene, and total xylenes were detected in the groundwater sample, but below Table 910-1 allowable concentrations. No impacted soil was removed from this location.

Soil/Geology Description:

Site geology includes sandy loam/clay.

Depth to Groundwater (feet BGS) 2 Number Water Wells within 1/2 mile radius: 4

If less than 1 mile, distance in feet to nearest Water Well 1268 None Surface Water 1426 None

Wetlands 1214 None

Springs 370 None

Livestock 2552 None

Occupied Building 687 None

Additional Spill Details Not Provided Above:

Empty box for additional spill details.

CORRECTIVE ACTIONS

#1 Supplemental Report Date: 09/28/2017

Cause of Spill (Check all that apply) Human Error Equipment Failure Historical-Unknown
 Other (specify) _____

Describe Incident & Root Cause (include specific equipment and point of failure)

On September 19, 2017, environmental testing activities associated with a produced water sump closure was conducted at the Erickson Birckle P25-4JI Tank Battery location. Shallow groundwater was encountered at two feet below ground surface in the sump's excavation. Due to operations conducted at the sump and the proximity to groundwater, minor environmental impacts were detected in the groundwater sample. Prior to backfilling the excavation, 50 pounds of Chemically Oxygenated Granular Activated Carbon (COGAC) was applied to the groundwater.

Describe measures taken to prevent the problem(s) from reoccurring:

The onsite equipment has been decommissioned.

Volume of Soil Excavated (cubic yards): _____

Disposition of Excavated Soil (attach documentation) Offsite Disposal Onsite Treatment
 Other (specify) _____

Volume of Impacted Ground Water Removed (bbls): _____

Volume of Impacted Surface Water Removed (bbls): _____

REQUEST FOR CLOSURE

Spill/Release Reports should be closed when impacts have been remediated or when further investigation and corrective actions will take place under an approved Form 27.

Basis for Closure: Corrective Actions Completed (documentation attached)
 Work proceeding under an approved Form 27

Form 27 Remediation Project No: _____

OPERATOR COMMENTS:

Empty box for operator comments.

I hereby certify all statements made in this form are to the best of my knowledge true, correct, and complete.

Signed: _____ Print Name: Erik Mickelson

Title: Senior HSE Representative Date: 09/28/2017 Email: erik.mickelson@anadarko.com

<u>COA Type</u>	<u>Description</u>

Attachment Check List

<u>Att Doc Num</u>	<u>Name</u>
401415332	TOPOGRAPHIC MAP
401415335	SITE MAP
401415336	ANALYTICAL RESULTS
401415338	ANALYTICAL RESULTS
401415340	ANALYTICAL RESULTS

Total Attach: 5 Files

General Comments

<u>User Group</u>	<u>Comment</u>	<u>Comment Date</u>
		Stamp Upon Approval

Total: 0 comment(s)