

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:
401392003
Date Received:
08/31/2017

FIR RESOLUTION FORM

CA Summary:

1 of 1 CAs from the FIR responded to on this Form

1 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 69175

Name of Operator: PDC ENERGY INC

Address: 1775 SHERMAN STREET - STE 3000

City: DENVER State: CO Zip: 80203

Contact Name and Telephone:

Name: _____

Phone: () Fax: ()

Email: _____

Additional Operator Contact:

Contact Name	Phone	Email
<u>Beau Hastings</u>		<u>beau.hastings@pdce.com</u>
<u>Sarah Bartlett</u>		<u>sarah.bartlett@pdce.com</u>
<u>Cynthia Stowell</u>		<u>cynthia.stowell@pdce.com</u>

COGCC INSPECTION SUMMARY:

FIR Document Number: 684904170

Inspection Date: 08/24/2017

FIR Submit Date: 08/24/2017

FIR Status: _____

Inspected Operator Information:

Company Name: PDC ENERGY INC

Company Number: 69175

Address: 1775 SHERMAN STREET - STE 3000

City: DENVER State: CO Zip: 80203

LOCATION - Location ID: 331712

Location Name: WELLS RANCH-65N63W Number: 11SWSW County: WELD

Qtrqtr: SWS Sec: 11 Twp: 5N Range: 63W Meridian: 6
W

Latitude: 40.406670 Longitude: -104.413300

FACILITY - API Number: 05-123-00 Facility ID: 265066

Facility Name: WELLS RANCH Number: 14-11

Qtrqtr: SWS Sec: 11 Twp: 5N Range: 63W Meridian: 6
W

Latitude: 40.406670 Longitude: -104.413300

CORRECTIVE ACTIONS:

1 CA# 95038

Corrective Action: Securely fasten all valves, pipes, and fittings to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 605.d. (24 hr CA)

Date: 08/25/2017

Response: CA COMPLETED

Date of Completion: 08/25/2017

Operator Comment: The AVO leak recorded at the Wells Ranch 14-11 wellhead is unable to be repaired without a workover rig and is considered delay of repair per CDPHE Regulation 7. The leak at the wellhead has been rolled into PDC's LDAR program, and will be addressed under this rule. The anticipated resolution will be the plug and abandonment (P&A) of this well, which once notifications and procedure approvals and is schedule for early 2018. Let me know if any further action is required or you have any questions.

COGCC Decision: **Not Approved**

COGCC Representative: Wellhead still leaking. Refer to inspection doc#684904550

OPERATOR COMMENT AND SUBMITTAL

Comment: The AVO leak recorded at the Wells Ranch 14-11 wellhead is unable to be repaired without a workover rig and is considered delay of repair per CDPHE Regulation 7. The leak at the wellhead has been rolled into PDC's LDAR program, and will be addressed under this rule. The anticipated resolution will be the plug and abandonment (P&A) of this well, which once notifications and procedure approvals and is schedule for early 2018. Let me know if any further action is required or you have any questions.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Cynthia Stowell

Signed: _____

Title: EHS Professional

Date: 8/31/2017 10:21:27 AM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
401392003	FIR RESOLUTION SUBMITTED

Total Attach: 1 Files