

Photo#1:

Overview of Location from NE Corner to SW; Matting is being installed over all of Pad, covered by top base.



October 4, 2017

Photo#2:

View along East Berm to South

*



Photo#3:

Site is bordered on East by Arapahoe National Wildlife Refuge.



October 4, 2017

Photo#4:

View at SE Corner where Equipment has compromised berm allowing Sediment Migration and exposing loose Piles of Soil which are potential pollution Sources



Photo#5:



October 4, 2017

Photo#6:

View to West along South Berm past the disturbed Corner.



Photo#7:

Weir gate to be installed at SW Corner.



October 4, 2017

Photo#8:

View of Cattle Guard on West Perimeter at what will be South Entry & flooded conditions of Access Road area.



October 4, 2017

Photo#10:

View From North Cattle Guard Entry along both sides of Access Road. North side indicated by arrow needs further BMPs installed.



Photo#11:



October 4, 2017

Photo#12:

Area at NW Corner where some Run On was occurring, caused by fencing disturbance of BMPs. Two Boxes of what appears to be DEF fluid in the Foreground.



October 4, 2017