

Photo#1:  
Overview of Location from Entry to North.



October 4, 2017



Photo#2:

Wattles have been dislodged from installation.



October 4, 2017



Photo#3:  
Canada Thistle along West side of Location.



October 4, 2017



#### Photo#4:

Retention/ Settling Pond at NW Corner where Weir gate is to be installed



October 4, 2017

## Photo#5:

View along East side of Location. Arrow indicates Area of Insert is indicated by arrow. Permanent SW BMPs need to be installed along East side of Site



October 4, 2017



Photo#6:  
Conductors Set with Cellar Covers Installed.



October 4, 2017