

**FORM
INSP**Rev
X/15

State of Colorado

Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

10/06/2017

Submitted Date:

10/10/2017

Document Number:

688300427**FIELD INSPECTION FORM**

Loc ID 320678 Inspector Name: Sherman, Susan On-Site Inspection ☐ 2A Doc Num: _____

Operator Information:OGCC Operator Number: 10646Name of Operator: BISON EXPLORATION LLCAddress: PO BOX 1168City: DENVER State: CO Zip: 80202**Status Summary:**

- ☒ THIS IS A FOLLOW UP INSPECTION
☒ FOLLOW UP INSPECTION REQUIRED
☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:5 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
O&G, Bison	720-644-6997	ops@bisonog.com	All inspections
Extraction		COGCCInspections@extracti onog.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
204438	WELL	PR	05/03/1982	GW	005-06523	Cavanaugh 3	PR

General Comment:[Form 10 in system to change operator.](#)

LocationOverall Good: ☐**Signs/Marker:**

Type	BATTERY		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment: 303-481-2844 is Bison Oil & Gas

Corrective Action: Date:

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Venting:**

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities									
Facility ID:	204438	Type:	WELL	API Number:	005-06523	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:		PR.							
Corrective Action:								Date:	

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Check Dams	Fail					
Blankets	Fail					

Comment: Sediment leaving locations going ~200' into crop field (see attached photos). Sediment offsite starts at GPS 39.69756, -104.53913.
Corrective action not completed from inspection #688300150.

Corrective Action: Install or repair required BMPs per Rule 1002.f.

Date: 10/06/2017

Pits: ☐ NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
688300450	Bison Exploration Cavanaugh 3 Reinspection	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4270674