

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

401430016

Date Received:

10/16/2017

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

2 of 2 CAs from the FIR responded to on this Form

2 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 100322

Name of Operator: NOBLE ENERGY INC

Address: 1625 BROADWAY STE 2200

City: DENVER State: CO Zip: 80202

Contact Name and Telephone:

Name: _____

Phone: () _____ Fax: () _____

Email: _____

Additional Operator Contact:

Contact Name

Phone

Email

Abby Bazin

720-587-2356

Abby.Bazin@nblenergy.com

Tesla Dougherty

970-304-5245

tesla.dougherty@nblenergy.com

COGCC INSPECTION SUMMARY:

FIR Document Number: 682402645

Inspection Date: 08/17/2017

FIR Submit Date: 08/22/2017

FIR Status: _____

Inspected Operator Information:

Company Name: NOBLE ENERGY INC

Company Number: 100322

Address: 1625 BROADWAY STE 2200

City: DENVER State: CO Zip: 80202

LOCATION - Location ID: 445209

Location Name: LC11-13 Number: Pad County: _____

Qtrqr: SWS Sec: 11 Twp: 9N Range: 59W Meridian: 6
W

Latitude: 40.759150 Longitude: -103.951390

FACILITY - API Number: 05-123- -00 Facility ID: 445209

Facility Name: LC11-13 Number: Pad

Qtrqr: SWS Sec: 11 Twp: 9N Range: 59W Meridian: 6
W

Latitude: 40.759150 Longitude: -103.951390

CORRECTIVE ACTIONS:

1 CA# 94429

Corrective Action: Perform reclamation along portions of the interim reclamation area in accordance to Rule 1003. Establish vegetation with total perennial, non-invasive uniform plant cover of at least eighty (80) percent of reference area levels. Use a seed mixture requested by the surface owner, or a mixture prescribed by the local county NRCS. Ensure erosion controls are implemented to stabilize the seeded soil, and continue to monitor and manage this site until the location meets Rule 1003 standards.

Date: 10/16/2017

Response: CA COMPLETED

Date of Completion: 10/13/2017

Operator Comment: At the time of this inspection, construction activities on this pad were not yet complete and interim construction had not yet been conducted. Interim reclamation is tentatively scheduled for December 2017, pending completion of site construction activities.

COGCC Decision: _____

COGCC Representative: _____

2 CA# 94430

Corrective Action: Install or repair required BMPs per Rule 1002.f. in accordance with good engineering practices. Corrective actions from the previous inspections were not resolved therefore the corrective action dates on this inspection remain the same from the previous inspections.

Date: 05/09/2017

Response: CA COMPLETED

Date of Completion: 10/13/2017

Operator Comment: The BMPs were improved and repaired, as shown on the attachment.

COGCC Decision: _____

COGCC Representative: _____

OPERATOR COMMENT AND SUBMITTAL

Comment: _____

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Tesla Dougherty

Signed: _____

Title: EHS Tech

Date: 10/16/2017 8:36:17 AM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
------------------------	--------------------

401430028	Holliday Tombstone Response
-----------	-----------------------------

Total Attach: 1 Files