

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
 Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

401347527

Date Received:

10/16/2017

Spill report taken by:

CHESSON, BOB

Spill/Release Point ID:

450831

SPILL/RELEASE REPORT (SUPPLEMENTAL)

This form is to be submitted by the party responsible for the oil and gas spill or release. Refer to COGCC Rule 906.b. for reporting requirements of spills or releases of E&P Waste or produced fluids. Submit a Site Investigation and Remediation Workplan (Form 27) when requested by the Director.

OPERATOR INFORMATION

Name of Operator: <u>KERR MCGEE OIL & GAS ONSHORE LP</u>	Operator No: <u>47120</u>	Phone Numbers
Address: <u>P O BOX 173779</u>		Phone: <u>(720) 929-6368</u>
City: <u>DENVER</u>	State: <u>CO</u>	Mobile: <u>(785) 691-7788</u>
Zip: <u>80217-3779</u>		Email: <u>Mike.Dinkel@anadarko.com</u>
Contact Person: <u>Mike Dinkel</u>		

INITIAL SPILL/RELEASE REPORT

Initial Spill/Release Report Doc# 401294414

Initial Report Date: 05/26/2017 Date of Discovery: 05/25/2017 Spill Type: Recent Spill

Spill/Release Point Location:

Location of Spill/Release: QTRQTR SESE SEC 10 TWP 1N RNG 63W MERIDIAN 6

Latitude: 40.059150 Longitude: -104.415158

Municipality (if within municipal boundaries): _____ County: WELD

Reference Location:

Facility Type: TANK BATTERY ☐ Facility/Location ID No _____
☒ No Existing Facility or Location ID No.
☐ Well API No. (Only if the reference facility is well) 05- -

Fluid(s) Spilled/Released (please answer Yes/No):

Was one (1) barrel or more spilled outside of berms or secondary containment? Yes

Secondary containment, including walls & floor regardless of construction material, must be sufficiently impervious to contain any discharge from primary containment until cleanup occurs.

Were Five (5) barrels or more spilled? Yes

Estimated Total Spill Volume: use same ranges as others for values

Estimated Oil Spill Volume(bbl): 0 Estimated Condensate Spill Volume(bbl): 0

Estimated Flow Back Fluid Spill Volume(bbl): 0 Estimated Produced Water Spill Volume(bbl): >=100

Estimated Other E&P Waste Spill Volume(bbl): 0 Estimated Drilling Fluid Spill Volume(bbl): 0

Specify: _____

Land Use:

Current Land Use: CROP LAND Other(Specify): _____

Weather Condition: Sunny ~ 70 degrees F.

Surface Owner: FEE Other(Specify): _____

Check if impacted or threatened by spill/Release (please answer Yes/No to all that apply):

Waters of the State ☐ Residence/Occupied Structure ☐ Livestock ☐ Public Byway ☐ Surface Water Supply Area ☐

As defined in COGCC 100-Series Rules

Describe what is known about the spill/release event (what happened -- including how it was stopped, contained, and recovered):

On May 25, 2017, a release occurred when bore mud mixed with produced water and fresh water was applied to the ground surface in SESE Sec.10-1N-63W and at a Noble Energy construction site. Produced water originated from the Fehr 16N-32HZ and Land Fed 13N-32HZ production facilities. Assessment and incident investigation activities are ongoing and will be summarized in a forthcoming Supplemental Form 19 Spill/Release Report. A topographic Site Location Map showing the geographic setting of the release is provided as Figure 1.

List Agencies and Other Parties Notified:

OTHER NOTIFICATIONS

Date	Agency/Party	Contact	Phone	Response
5/26/2017	County	Tom Parko	-email	
5/26/2017	County	Troy Swain	-email	
5/26/2017	County	Roy Rudisill	-email	
5/26/2017	Land owner	Private	-phone	

SPILL/RELEASE DETAIL REPORTS

#1	Supplemental Report Date: 09/18/2017		
FLUIDS	BBL's SPILLED	BBL's RECOVERED	Unknown
OIL	0	0	<input type="checkbox"/>
CONDENSATE	0	0	<input type="checkbox"/>
PRODUCED WATER	150	0	<input type="checkbox"/>
DRILLING FLUID	0	0	<input type="checkbox"/>
FLOW BACK FLUID	0	0	<input type="checkbox"/>
OTHER E&P WASTE	0	0	<input type="checkbox"/>
specify: _____			
Was spill/release completely contained within berms or secondary containment? <u>NO</u> Was an Emergency Pit constructed? <u>NO</u>			
<i>Secondary containment, including walls & floor regardless of construction material, must be sufficiently impervious to contain any discharge from primary containment until cleanup occurs.</i>			
A Form 15 Pit Report shall be submitted within 30 calendar days after the construction of an emergency pit			
Impacted Media (Check all that apply) <input checked="" type="checkbox"/> Soil <input type="checkbox"/> Groundwater <input type="checkbox"/> Surface Water <input type="checkbox"/> Dry Drainage Feature			
Surface Area Impacted: Length of Impact (feet): _____		Width of Impact (feet): _____	
Depth of Impact (feet BGS): _____		Depth of Impact (inches BGS): _____	
How was extent determined?			
On May 25, 2017, a release occurred when bore mud mixed with produced water and fresh water was applied to the ground surface in SESE Sec.10-1N-63W and at a Noble Energy construction site. Produced water originated from the Fehr 16N-32HZ and Land Fed 13N-32HZ production facilities. Characterization samples were collected from bore mud from the Noble Energy pipe bore inlet and outlet, and soil and water from the bore mud land application site and adjacent pond. Soil and water samples were submitted to Origins Laboratory and Summit Scientific for analysis of various analytes, including: volatile organic compounds (VOCs) including benzene, toluene, ethylbenzene, and total xylenes (BTEX), total petroleum hydrocarbons (TPH) - gasoline range organics (GRO) by USEPA Method 8260C, TPH - diesel and oil range organics (DRO and ORO) by USEPA Method 8015, electrical conductivity (EC), pH, and arsenic by USEPA Method 6020A. Analytical results indicated that constituent concentrations in the samples collected from these locations were below the applicable COGCC Table 910-1 standards, with the exception of arsenic at the mud land application site. Seven (7) background native soil samples (BG02 – BG08) were collected from areas adjacent to the mud land application site and were submitted to Summit Scientific for analysis of arsenic by USEPA Method 6020A. Analytical results indicated that arsenic concentrations in the 7 background native soil samples were also above the COGCC Table 910-1 standard.			
Soil/Geology Description:			
Clay			

Attachment Check List

<u>Att Doc Num</u>	<u>Name</u>
401347527	SPILL/RELEASE REPORT(SUPPLEMENTAL)
401348331	TOPOGRAPHIC MAP
401400981	ANALYTICAL RESULTS
401400991	ANALYTICAL RESULTS
401401019	SITE MAP
401435250	FORM 19 SUBMITTED

Total Attach: 6 Files

General Comments

<u>User Group</u>	<u>Comment</u>	<u>Comment Date</u>
		Stamp Upon Approval

Total: 0 comment(s)