

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

10/23/2017

Submitted Date:

10/24/2017

Document Number:

688000092**FIELD INSPECTION FORM**Loc ID _____ Inspector Name: YOUNG, ROB On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 7800Name of Operator: BEREN CORPORATIONAddress: 2020 N BRAMBLEWOOD STREETCity: WICHITA State: KS Zip: 67206**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:2 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
Reynolds, Rodney	316-337-8340	reynoldsr@berexco.com	
Axelson, John		john.axelson@state.co.us	

General Comment:Environmental inspection related to north pit closure, Rem#10290.

Environmental**Spill/Remediation:**

Comment: Met consultant and excavation contractor on site. Additional oil had accumulated in the northern excavation. Western portion of the excavation "western sub-pit" appears to be clean and once documentation is provided, backfilling may be appropriate to allow access to excavate impacted soils to the east.

Corrective Action: Maintain an excavation in the northern portion of the pit that is open to the water table and configured to allow periodic removal of oil impacted groundwater.

Date: 10/31/2017

Emission Control Burner (ECB): _____

Comment: _____

Pilot: _____ Wildlife Protection Devices (fired vessels): _____

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
688000093	Location photographs	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4283257