

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:
401439127
Date Received:
10/24/2017

FIR RESOLUTION FORM

CA Summary:

2 of 2 CAs from the FIR responded to on this Form

2 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10559
Name of Operator: SOUTHLAND ROYALTY COMPANY LLC
Address: 400 WEST 7TH STREET
City: FORT WORTH State: TX Zip: 76102

Contact Name and Telephone:
Name:
Phone: () Fax: ()
Email:

Additional Operator Contact:

Contact Name	Phone	Email
<u>Hampton, John</u>	<u>505-330-4377</u>	<u>jhampton@ctfieldsvcs.com</u>
<u>Grigg, Robbie</u>	<u>817-334-7842</u>	<u>rgrigg@mspartner.com</u>
<u>Labowskie, Steve</u>		<u>steve.labowskie@state.co.us</u>
<u>Howe, Mike</u>	<u>505-330-3058</u>	<u>MHowe@ctfieldsvcs.com</u>
<u>Leonard, Mike</u>		<u>mike.leonard@state.co.us</u>

COGCC INSPECTION SUMMARY:

FIR Document Number: 685303793
Inspection Date: 09/25/2017 FIR Submit Date: 09/27/2017 FIR Status:

Inspected Operator Information:

Company Name: SOUTHLAND ROYALTY COMPANY LLC Company Number: 10559
Address: 400 WEST 7TH STREET
City: FORT WORTH State: TX Zip: 76102

LOCATION - Location ID: 334038

Location Name: DUELL 32-6-N32N6W Number: 5NENE County: LA PLATA
Qtrqtr: NENE Sec: 5 Twp: 32N Range: 6W Meridian: N
Latitude: 37.050840 Longitude: -107.518400

FACILITY - API Number: 05-067-00 Facility ID: 293766

Facility Name: DUELL 32-6 Number: 5-3
Qtrqtr: NENE Sec: 5 Twp: 32N Range: 6W Meridian: N
Latitude: 37.050840 Longitude: -107.518400

CORRECTIVE ACTIONS:

1 CA# 103203

Corrective Action: Comply with Rule 603.f. For unused, unmarked flowline risers 24 hrs to lock out tag out. 30 days to remove riser.

Date: 10/28/2017

Response: CA COMPLETED

Date of Completion: 10/24/2017

Operator Comment: See attached. See pictures of corrective action request. Request follow up inspection.

COGCC Decision: Approved

COGCC Representative: The flowline risers identified during the inspection may belong to a different operator. Additional research will be completed by COGCC to determine owner of identified risers.

2 CA# 103204

Corrective Action: Install or repair required BMPs to comply with Rule 1002.f.

Date: 10/28/2017

Response: CA COMPLETED

Date of Completion: 10/24/2017

Operator Comment: See attached pictures. Ready for follow up inspection

COGCC Decision: Approved pending re-inspection

COGCC Representative: Follow up inspection to be completed.

OPERATOR COMMENT AND SUBMITTAL

Comment: See attached picture documenting our compliance with inspectors corrective action comment.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Robbie Grigg

Signed: _____

Title: Supvr Regulatory

Date: 10/24/2017 11:48:02 AM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
401439127	FIR RESOLUTION SUBMITTED
401439130	Duell 5-1 Ditch
401439132	Duell 5-1 Drainage
401439134	Duell 5-1 Slope
401439153	

Total Attach: 5 Files