

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:
401442807
Date Received:
10/27/2017

FIR RESOLUTION FORM

CA Summary:

1 of 1 CAs from the FIR responded to on this Form

1 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10646
Name of Operator: BISON EXPLORATION LLC
Address: PO BOX 1168
City: DENVER State: CO Zip: 80202
Contact Name and Telephone:
Name:
Phone: () Fax: ()
Email:

Additional Operator Contact:

Contact Name Phone Email
Jeff Rickard 720 737-5144 jrickard@extractionog.com

COGCC INSPECTION SUMMARY:

FIR Document Number: 688300427
Inspection Date: 10/06/2017 FIR Submit Date: 10/10/2017 FIR Status:

Inspected Operator Information:

Company Name: BISON EXPLORATION LLC Company Number: 10646
Address: PO BOX 1168
City: DENVER State: CO Zip: 80202

LOCATION - Location ID: 320678

Location Name: CAVANAUGH-64S64W Number: 15SESW County: ARAPAHOE
Qtrqr: SESW Sec: 15 Twp: 4S Range: 64W Meridian: 6
Latitude: 39.697060 Longitude: -104.539010

FACILITY - API Number: 05-005-00 Facility ID: 204438

Facility Name: Cavanaugh Number: 3
Qtrqr: SESW Sec: 15 Twp: 4S Range: 64W Meridian: 6
Latitude: 39.697060 Longitude: -104.539010

CORRECTIVE ACTIONS:

1 CA# 104591

Corrective Action: Install or repair required BMPs per Rule 1002.f. Date: 10/06/2017

Response: CA COMPLETED Date of Completion: 10/20/2017

Operator Comment: Stormwater issues havbe been corrected, please see attached report.

COGCC Decision: Approved

COGCC
Representative:

OPERATOR COMMENT AND SUBMITTAL

Comment:

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Jeff Rickard

Signed:

Title: Regulatory COmpliance Coo

Date: 10/27/2017 1:06:28 PM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
401442807	FIR RESOLUTION SUBMITTED
401442815	Repair details

Total Attach: 2 Files