

Stormwater Inspection

November 3, 2017

Operator: PETROSHARE CORPORATION- 10454

Location ID: 322194

Elbert County, CO

NENE Section 20 T6S R64W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos

Location Name: NORDMAN TRUST #41-20

Location ID: 322194



Google Earth aerial imagery taken 6/14/2016 illustrating well location during operations. A point of discharge was observed during the November 3, 2017 inspection along the northeastern well pad (highlighted in the red circle). A portion of the western cut slope has stormwater run-on which is causing degradation to the location. Also, erosion issues were also observed along the access road. See the following photos for more detail.

Inspection Photos
Location Name: NORDMAN TRUST #41-20
Location ID: 322194



Photo 1. Photo taken of the Operator sign at location.



Photo 2. Photo taken from the well location, facing North. Remove or remediate stained soil per Rule 906.a.

Inspection Photos
Location Name: NORDMAN TRUST #41-20
Location ID: 322194



Photo 3. Photo taken from the northeast well pad, facing East. Rip-rap has been installed but does not appear to be a sufficient BMP as active gully erosion is evident. Operator needs to repair gully erosion and install sufficient BMPs.



Photo 4. Photo taken downgradient from the gully erosion, facing West. See comments under Photo 3.

Inspection Photos
Location Name: NORDMAN TRUST #41-20
Location ID: 322194



Photo 5. Photo taken from the western well pad location, facing West. Appears stormwater run-on onto the location is causing gully erosion along the western cut slope which is causing degradation to the location. Operator needs to repair gully erosion and install sufficient BMPs.



Photo 6. Photo taken from a portion of the access road, facing East. Rill erosion forming into gully erosion is evident along the access road. Operator needs to repair erosion and install sufficient BMPs.