



Photo 1. View of the western portion of the project area from the northwestern corner facing southward.





Photo 2. View of the southern portion of the project area from the well pad entrance facing westward. Erosion is occurring where runoff becomes concentrated around project facilities and flows off the well pad.

