

State of Colorado  
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

401444092

Date Received:

10/30/2017

## FIR RESOLUTION FORM

### CA Summary:

1 of 1 CAs from the FIR responded to on this Form

1 CA Completed  
0 Factual Review Request

### OPERATOR INFORMATION

OGCC Operator Number: 10000

Name of Operator: BP AMERICA PRODUCTION COMPANY

Address: 380 AIRPORT RD

City: DURANGO State: CO Zip: 81303

Contact Name and Telephone:

Name: \_\_\_\_\_

Phone: ( ) Fax: ( )

Email: \_\_\_\_\_

### Additional Operator Contact:

Contact Name

Phone

Email

Beebe, Sabre

970-375-7530

Sabre.Beebe@bp.com

Inspections, All

SanJuanCOGCC@bp.com

Labowskie, Steve

steve.labowskie@state.co.us

Leonard, Mike

mike.leonard@state.co.us

### COGCC INSPECTION SUMMARY:

FIR Document Number: 685303685

Inspection Date: 08/23/2017

FIR Submit Date: 08/23/2017

FIR Status: \_\_\_\_\_

### Inspected Operator Information:

Company Name: BP AMERICA PRODUCTION COMPANY

Company Number: 10000

Address: 380 AIRPORT RD

City: DURANGO State: CO Zip: 81303

### LOCATION - Location ID: 325824

Location Name: ARCHULETA/DIX GAS UNIT- N34N6W Number: 9SWSE County: LA PLATA

Qtrqr: SWSE Sec: 9 Twp: 34N Range: 6W Meridian: N

Latitude: 37.224891 Longitude: -107.529684

### FACILITY - API Number: 05-067- -00 Facility ID: 215433

Facility Name: ARCHULETA-DIX Number: 1

Qtrqr: SWSE Sec: 9 Twp: 34N Range: 6W Meridian: N

Latitude: 37.224891 Longitude: -107.529684

### CORRECTIVE ACTIONS:

1 ☒ CA# 94960

Corrective Action: Install or repair required BMPs to comply with Rule 1002.f. Refer to the 1002.f guidance document for further details.

Date: 08/17/2017

Response: CA COMPLETED

Date of Completion: 08/23/2017

Operator Comment: the existing erosion channel was filled and a rock run down installed to prevent future erosion. See attached photos

COGCC Decision: Approved via an AMI

COGCC Representative: Approved using operator supplied photo documentation.

#### OPERATOR COMMENT AND SUBMITTAL

Comment: the existing erosion channel was filled and a rock run down installed to prevent future erosion. See attached photos  
Additionally musk thistle rosettes were manually removed from location

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Sabre Beebe

Signed: \_\_\_\_\_

Title: Compliance Specialist

Date: 10/30/2017 10:52:05 AM

### ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
------------------------	--------------------

401444092	FIR RESOLUTION SUBMITTED
401444312	Closure photos

Total Attach: 2 Files