

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

11/07/2017

Submitted Date:

11/09/2017

Document Number:

689400631

FIELD INSPECTION FORM

Loc ID 324468 Inspector Name: CONKLIN, CURTIS On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 77330
 Name of Operator: SG INTERESTS I LTD
 Address: 100 WAUGH DR SUITE 400
 City: HOUSTON State: TX Zip: 77007

Findings:

- 4 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

Contact Information:

Contact Name	Phone	Email	Comment
Arthur, Denise		denise.arthur@state.co.us	
Ash, Margaret		margaret.ash@state.co.us	
Labowskie, Steve		steve.labowskie@state.co.us	
Inspections, All		inspection@sginterests.com	All Inspections
Kellerby, Shaun		shaun.kellerby@state.co.us	NW Supervisor

General Comment:

[This is a routine field inspection, any corrective actions not addressed from previous inspections are still applicable.](#)

[After review of FIRR form and communication with Reclamation Supervisor, this inspection is to address the sewer tank related to the man-camp. See stormwater section of inspection.](#)

Location

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Overall Good:

Spills:

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

Venting:

Yes/No			
Comment:	<input type="text"/>		
Corrective Action:		Date:	<input type="text"/>

Flaring:

Type		
Comment:	<input type="text"/>	
Corrective Action:		Date: <input type="text"/>

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: Sewer tank located next to man-camp and at edge of location. Location does not appear to have sufficient down gradient perimeter controls for containment of unexpected release from tank.

Corrective Action: **Install BMPs.**

Date: 11/16/2017

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401454018	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4298068
689400632	Falcon Seaboard Man-camp	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4298065