

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

401461002

Date Received:

11/16/2017

FIR RESOLUTION FORM

CA Summary:

1 of 1 CAs from the FIR responded to on this Form

1 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 81490

Name of Operator: ST CROIX OPERATING INC

Address: P O BOX 13799

City: DENVER State: CO Zip: 80201

Contact Name and Telephone:

Name: _____

Phone: () Fax: ()

Email: _____

Additional Operator Contact:

Contact Name

Phone

Email

dnr_cogccenforcement@state.co.us

stcroixexp@aol.com

[Arthur, Denise](#)

denise.arthur@state.co.us

nrsavio@aol.com

[Andy Peterson](#)

[970-203-4263](tel:970-203-4263)

andy@petersonenergyoperating.com

COGCC INSPECTION SUMMARY:

FIR Document Number: 682502777

Inspection Date: 11/09/2017

FIR Submit Date: 11/10/2017

FIR Status: _____

Inspected Operator Information:

Company Name: ST CROIX OPERATING INC

Company Number: 81490

Address: P O BOX 13799

City: DENVER State: CO Zip: 80201

LOCATION - Location ID: 452312

Location Name: SCOUT-NIEBUR Number: 1 County: _____

Qtrqr: SESE Sec: 35 Twp: 2S Range: 51W Meridian: 6

Latitude: 39.832090 Longitude: -103.050210

FACILITY - API Number: 05-121- -00 Facility ID: 452312

Facility Name: SCOUT-NIEBUR Number: 1

Qtrqr: SESE Sec: 35 Twp: 2S Range: 51W Meridian: 6

Latitude: 39.832090 Longitude: -103.050210

CORRECTIVE ACTIONS:

1 ☒ CA# 110226

Corrective Action: Properly select, install and maintain required site specific stormwater and sediment control BMPs in such a manner that minimizes erosion, transport of sediment offsite, and site degradation per 1002.f

Date: 11/09/2017

Operator
Comment:

St. Croix believes one critical BMP for sites in this area is minimal topsoil disturbance, followed by quick restoration of any disturbed areas. The undisturbed topsoil and CRP grass coverage under the rig and trafficked areas held up nicely for the duration of the drilling phase. No breakthrough of grass coverage occurred in the trafficked areas. These areas will restore naturally in a short time frame, with minimal lasting damage.

The segregated topsoil pile on the south end of location was hydromulch stabilized. The subsoil piles around the reserve pit were not hydromulched stabilized. St. Croix plans to begin interim pit closure operations in approximately two weeks. During this interim restoration the subsoil piles will be partially reincorporated into the reserve pit. Soil stabilization installed during initial pit construction will be destroyed during interim reclamation. As a result the decision was made not to stabilize the subsoil piles upon initial construction. Following interim reclamation operations, St. Croix will again evaluate what form of soil stabilization is required.

11/15/2017: subsoil piles stabilized with hydromulch.

COGCC Decision: Approved pending re-inspection

COGCC
Representative:

COGCC does not agree with operators assessment within "Operator Comment".

Operator has indicated soil stockpiles have been stabilized. "Approved pending re-inspection" of the FIR resolution acknowledges that the Oil and Gas Conservation Commission has received the notice. It is not an acknowledgement that the corrective action has been passed. A field inspection will be conducted to evaluate compliance with COGCC standards.

OPERATOR COMMENT AND SUBMITTAL

Comment: 11/15/2017: subsoil piles stabilized with hydromulch.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Paul Gottlob

Signed: _____

Title: Regulatory & Engin. Tech.

Date: 11/16/2017 6:32:40 AM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

Document Number **Description**

401461002	FIR RESOLUTION SUBMITTED
-----------	--------------------------

Total Attach: 1 Files