

State of Colorado  
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:  
401450923  
Date Received:  
11/06/2017

## FIR RESOLUTION FORM

### CA Summary:

2 of 2 CAs from the FIR responded to on this Form

2 CA Completed  
0 Factual Review Request

### OPERATOR INFORMATION

OGCC Operator Number: 69175

Name of Operator: PDC ENERGY INC

Address: 1775 SHERMAN STREET - STE 3000

City: DENVER State: CO Zip: 80203

Contact Name and Telephone:

Name: \_\_\_\_\_

Phone: ( ) Fax: ( )

Email: \_\_\_\_\_

### Additional Operator Contact:

Contact Name

Phone

Email

Cynthia Stowell

cynthia.stowell@pdce.com

Aaron Clyncke

aaron.clyncke@pdce.com

### COGCC INSPECTION SUMMARY:

FIR Document Number: 689300338

Inspection Date: 10/26/2017

FIR Submit Date: 10/26/2017

FIR Status: \_\_\_\_\_

### Inspected Operator Information:

Company Name: PDC ENERGY INC

Company Number: 69175

Address: 1775 SHERMAN STREET - STE 3000

City: DENVER State: CO Zip: 80203

### LOCATION - Location ID: 330681

Location Name: MOORE-65N67W Number: 13CSW County: WELD

Qtrqtr: CSW Sec: 13 Twp: 5N Range: 67W Meridian: 6

Latitude: 40.395888 Longitude: -104.846256

### FACILITY - API Number: 05-123- -00 Facility ID: 251652

Facility Name: MOORE Number: 13-35

Qtrqtr: CSW Sec: 13 Twp: 5N Range: 67W Meridian: 6

Latitude: 40.395888 Longitude: -104.846256

### CORRECTIVE ACTIONS:

1 ☒ CA# 107600

Corrective Action: Comply with Rule 603.f .  
For unused , unmarked flowline risers 24 hrs to lock out tag out. 30 days to remove riser.

Date: 11/26/2017

Response: CA COMPLETED

Date of Completion: 10/26/2017

Operator Comment: Well is outside the 1000' feet from structures. Line has been pressure tested and valve plugged. Valve is locked out/tagged out with for future use tag and pressure test date applied. Riser will not be removed at this time.  
Photo of corrective action attached.



COGCC Decision: Approved

COGCC Representative: 1" steel riser at wellhead has been LOTO and labeled.

2 ☒ CA# 107601

Corrective Action: Install or repair required BMPs per Rule 1002.f.

Date: 11/26/2017

Response: CA COMPLETED

Date of Completion: 11/06/2017

Operator Comment: BMPs have been corrected

COGCC Decision: Approved

COGCC Representative: Location erosion has been repaired

#### OPERATOR COMMENT AND SUBMITTAL

Comment:

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Cynthia Stowell

Signed: \_\_\_\_\_

Title: EHS Professional

Date: 11/6/2017 12:39:31 PM

#### **ATTACHMENT LIST**

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
401450923	FIR RESOLUTION SUBMITTED
401450927	LOTO

Total Attach: 2 Files