

Inspection Photos

11/14/2017

Operator: EXTRACTION OIL & GAS INC - 10459

Location ID: 323581

Inspection Doc. Number: 682502815

Weld County, CO

Aaron Trujillo
NE Reclamation Specialist
COGCC

Inspection Photos
Operator: EXTRACTION OIL & GAS INC - 10459
Location ID: 323581



Photo 1: Photo taken from the west end of the location, facing east. Previous inspections documented that inadequate stormwater and sediment control BMPs have been installed with good engineering practices, and required operator to install or repair required BMPs per rule 1002.f. Operator may have implemented surface roughening, however this is not clear. If surface roughening had been installed, BMP would be insufficient/inadequate as surface roughening is a temporary control that should be used in conjunction with other BMPs. Photo shows no additional stormwater and sediment control BMPs appear to have been implemented on the location.



Photo 2: Photo taken from the west end of the location, facing west. See comments under photo 1.

Inspection Photos
Operator: EXTRACTION OIL & GAS INC - 10459
Location ID: 323581



Photo 3: Photo taken from the west end of the location, facing east. See comments under photo 1.



Photo 4: Photo taken from the west end of the location, facing northeast. See comments under photo 1.

Inspection Photos
Operator: EXTRACTION OIL & GAS INC - 10459
Location ID: 323581



Photo 5: Photo taken from the northwest end of the location, facing east. See comments under photo 1.



Photo 6: Photo taken from the northeast end of the location, facing southeast. See comments under photo 1.