

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

401461889

Date Received:

11/16/2017

FIR RESOLUTION FORM

CA Summary:

2 of 2 CAs from the FIR responded to on this Form

2 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10611
Name of Operator: LONGS PEAK RESOURCES LLC
Address: 2323 S SHEPHERD SUITE 1150
City: HOUSTON State: TX Zip: 77019

Contact Name and Telephone:
Name:
Phone: () Fax: ()
Email:

Additional Operator Contact:

Contact Name	Phone	Email
David Clarkson	214-534-9569	dclarkson@vrtxep.com

COGCC INSPECTION SUMMARY:

FIR Document Number: 682402874
Inspection Date: 10/06/2017 FIR Submit Date: 10/12/2017 FIR Status:

Inspected Operator Information:

Company Name: LONGS PEAK RESOURCES LLC Company Number: 10611
Address: 2323 S SHEPHERD SUITE 1150
City: HOUSTON State: TX Zip: 77019

LOCATION - Location ID: 438066

Location Name: RAILAY Number: 28-3-1CH County:
Qtrqr: NENW Sec: 28 Twp: 12N Range: 66W Meridian: 6
Latitude: 40.985310 Longitude: -104.783590

FACILITY - API Number: 05-123-00 Facility ID: 438066

Facility Name: RAILAY Number: 28-3-1CH
Qtrqr: NENW Sec: 28 Twp: 12N Range: 66W Meridian: 6
Latitude: 40.985310 Longitude: -104.783590

CORRECTIVE ACTIONS:

1 CA# 104893

Corrective Action: Comply with Rule 603.f. to control and manage weedy, annual vegetation to prevent weed waste and prevent spread of dispersing seeds onto adjacent lands. Date: 10/26/2017

Response: CA COMPLETED Date of Completion: 10/24/2017

Operator Comment: weedy, annual vegetation has been cleaned up around location to the point that it prevents weed waste and the spread of dispersing seeds onto adjacent lands in compliance with Rule 603.f.

COGCC Decision: Approved pending re-inspection

This is an acknowledgement that the document and attachment were received. The outcome of the performed

COGCC Representative: corrective action work will be determined on the ground during an inspection at a future date.

2 CA# 104894

Corrective Action: Install or repair required BMPs in accordance with good engineering practices per Rule 1002.f. Corrective actions from the previous inspection were not resolved and BMPs were not properly installed or sufficient; therefore, the corrective action dates on this inspection remain the same from the previous inspection.

Date: 08/17/2017

Response: CA COMPLETED

Date of Completion: 10/20/2017

Operator Comment: All BMPs are repaired in accordance with good engineering practices per Rule 1002.f.

COGCC Decision: Approved pending re-inspection

COGCC Representative: This is an acknowledgement that the document and attachment were received. COGCC staff will perform an on-the-ground inspection at a future date to determine whether the installed BMPs and repairs appear to be in compliance with Rule 1002.f.

OPERATOR COMMENT AND SUBMITTAL

Comment:

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: David Clarkson Signed:

Title: COO Date: 11/16/2017 3:51:49 PM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

Document Number	Description
401461889	FIR RESOLUTION SUBMITTED
401461976	Word Document with Pictures of repairs

Total Attach: 2 Files