

State of Colorado  
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:  
401469682

Date Received:  
11/28/2017

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

3 of 3 CAs from the FIR responded to on this Form

3 CA Completed  
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 83555

Name of Operator: SUNBURST INC

Address: 1401 E GIRARD STE 143

City: ENGLEWOOD State: CO Zip: 80110

Contact Name and Telephone:

Name: \_\_\_\_\_

Phone: ( ) \_\_\_\_\_ Fax: ( ) \_\_\_\_\_

Email: \_\_\_\_\_

Additional Operator Contact:

Contact Name

Phone

Email

Joe Mazotti

720-226-5791

ogp-co@comcast.net

COGCC INSPECTION SUMMARY:

FIR Document Number: 684904671

Inspection Date: 11/03/2017

FIR Submit Date: 11/03/2017

FIR Status: \_\_\_\_\_

Inspected Operator Information:

Company Name: SUNBURST INC

Company Number: 83555

Address: 1401 E GIRARD STE 143

City: ENGLEWOOD State: CO Zip: 80110

LOCATION - Location ID: 318773

Location Name: STATE-610N62W Number: 36SWSW County: WELD

Qtrqr: SWS Sec: 36 Twp: 10N Range: 62W Meridian: 6  
W

Latitude: 40.786600 Longitude: -104.274880

FACILITY - API Number: 05-123- -00 Facility ID: 242143

Facility Name: STATE Number: 1 (13-36)

Qtrqr: SWS Sec: 36 Twp: 10N Range: 62W Meridian: 6  
W

Latitude: 40.786600 Longitude: -104.274880

CORRECTIVE ACTIONS:

1 CA# 109423

Corrective Action: Repair and maintain lease road.

Date: 12/04/2017

Response: CA COMPLETED

Date of Completion: 11/20/2017

Operator Comment: Lease road has been repaired and will be maintained.

COGCC Decision: \_\_\_\_\_

COGCC  
Representative: \_\_\_\_\_

**2** CA# 109424

Corrective Action: Remove or remediate stained soil; Securely fasten all valves, pipes, and fittings to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 605.d.

Date: 12/04/2017

Response: CA COMPLETED

Date of Completion: 11/20/2017

Operator Comment: Stained soil as been removed and area remediated. All ll valves, pipes, and fittings have been securley fastened and inspected and to ensure good mechanical condition and inspections will take place at regular intervals and maintain in good mechanical condition.

COGCC Decision: \_\_\_\_\_

COGCC  
Representative: \_\_\_\_\_

**3** CA# 109425

Corrective Action: Install or repair required BMPs per Rule 1002.f.

Date: 12/04/2017

Response: CA COMPLETED

Date of Completion: 11/20/2017

Operator Comment: Stormwater erosion on E side of location repaired. Reseeding will take place in the spring of 2018.

COGCC Decision: \_\_\_\_\_

COGCC  
Representative: \_\_\_\_\_

#### OPERATOR COMMENT AND SUBMITTAL

Comment: Reseeding will take place in the spring of 2018.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Joe Mazotti

Signed: \_\_\_\_\_

Title: Agent

Date: 11/28/2017 2:21:14 PM

### ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
------------------------	--------------------

--	--

Total Attach: 0 Files