

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:
401471232

Date Received:
11/29/2017

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

3 of 3 CAs from the FIR responded to on this Form

3 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 100322

Name of Operator: NOBLE ENERGY INC

Address: 1001 NOBLE ENERGY WAY

City: HOUSTON State: TX Zip: 77070

Contact Name and Telephone:

Name:

Phone: () Fax: ()

Email:

Additional Operator Contact:

Contact Name	Phone	Email
Tesla Dougherty	970-304-5245	tesla.dougherty@nblebergy.com

COGCC INSPECTION SUMMARY:

FIR Document Number: 682502813

Inspection Date: 11/14/2017

FIR Submit Date: 11/16/2017

FIR Status:

Inspected Operator Information:

Company Name: NOBLE ENERGY INC

Company Number: 100322

Address: 1001 NOBLE ENERGY WAY

City: HOUSTON State: TX Zip: 77070

LOCATION - Location ID: 323052

Location Name: HIGHLAND-64N64W Number: 20NESW County:

Qtrqr: NESW Sec: 20 Twp: 4N Range: 64W Meridian: 6

Latitude: 40.296261 Longitude: -104.577481

FACILITY - API Number: 05-123-00 Facility ID: 323052

Facility Name: HIGHLAND-64N64W Number: 20NESW

Qtrqr: NESW Sec: 20 Twp: 4N Range: 64W Meridian: 6

Latitude: 40.296261 Longitude: -104.577481

CORRECTIVE ACTIONS:

1 CA# 110906

Corrective Action: Perform maintenance along access road. Implement BMPs as needed to prevent future degradation. This is the second inspection requiring maintenance.

Date: 11/02/2017

Response: CA COMPLETED

Date of Completion: 11/22/2017

Operator Comment: Road base has been removed and the gully has been repaired. Top soil and compost has been hauled in, the area was graded ripped and cross-ripped on November 17, 2017. This location was seeded, mulched and crimped on November 22, 2017

COGCC Decision:

COGCC
Representative:

2 CA# 110907

Corrective Action: Perform reclamation in accordance to COGCC 1000 series reclamation rules at well and access road. Ensure temporary stabilization controls are in place until more permanent vegetative stabilization has established. Reclamation activities shall be completed no later than 7/31/2017.

Date: 07/31/2017

Response: CA COMPLETED

Date of Completion: 11/22/2017

Operator Comment: Road base has been removed and the gully has been repaired. Top soil and compost has been hauled in, the area was graded ripped and cross-ripped on November 17, 2017. This location was seeded, mulched and crimped on November 22, 2017

COGCC Decision: _____

COGCC
Representative:

3 CA# 110908

Corrective Action: Repair erosion an install or repair required BMPs per Rule 1002.f

Date: 07/31/2017

Response: CA COMPLETED

Date of Completion: 11/22/2017

Operator Comment: Noble repaired the erosion in the access road by removing the road base, bringing in topsoil, and regrading. The regraded areas were seeded, mulched and crimped to control erosion.

COGCC Decision: _____

COGCC
Representative:

OPERATOR COMMENT AND SUBMITTAL

Comment:

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Tesla Dougherty

Signed: _____

Title: EHS Specialist

Date: 11/29/2017 2:40:56 PM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

Document Number **Description**

<u>Document Number</u>	<u>Description</u>

Total Attach: 0 Files