

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

401471232

Date Received:

11/29/2017

FIR RESOLUTION FORM

CA Summary:

3 of 3 CAs from the FIR responded to on this Form

3 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 100322

Name of Operator: NOBLE ENERGY INC

Address: 1001 NOBLE ENERGY WAY

City: HOUSTON State: TX Zip: 77070

Contact Name and Telephone:

Name: _____

Phone: () Fax: ()

Email: _____

Additional Operator Contact:

Contact Name

Tesla Dougherty

Phone

970-304-5245

Email

tesla.dougherty@nobleenergy.com

COGCC INSPECTION SUMMARY:

FIR Document Number: 682502813

Inspection Date: 11/14/2017

FIR Submit Date: 11/16/2017

FIR Status: _____

Inspected Operator Information:

Company Name: NOBLE ENERGY INC

Company Number: 100322

Address: 1001 NOBLE ENERGY WAY

City: HOUSTON State: TX Zip: 77070

LOCATION - Location ID: 323052

Location Name: HIGHLAND-64N64W Number: 20NESW County: _____

Qtrqr: NESW Sec: 20 Twp: 4N Range: 64W Meridian: 6

Latitude: 40.296261 Longitude: -104.577481

FACILITY - API Number: 05-123-00 Facility ID: 323052

Facility Name: HIGHLAND-64N64W Number: 20NESW

Qtrqr: NESW Sec: 20 Twp: 4N Range: 64W Meridian: 6

Latitude: 40.296261 Longitude: -104.577481

CORRECTIVE ACTIONS:

1 ☒ CA# 110906

Corrective Action: Perform maintenance along access road. Implement BMPs as needed to prevent future degradation. This is the second inspection requiring maintenance.

Date: 11/02/2017

Response: CA COMPLETED

Date of Completion: 11/22/2017

Operator Comment: Road base has been removed and the gully has been repaired. Top soil and compost has been hauled in, the area was graded ripped and cross-ripped on November 17, 2017. This location was seeded, mulched and crimped on November 22, 2017

COGCC Decision: Approved pending re-inspection

COGCC Representative: Corrective action required operator to perform maintenance on access road leading to active battery location, where deep ruts and erosion formed. COGCC is unclear if operator has performed reclamation over the entire access road and active battery adjacent to the PA'd well instead. "Approved pending re-inspection" of the FIR resolution acknowledges that the Oil and Gas Conservation Commission has received the notice. It is not an acknowledgement that the corrective action has been passed. Operator has not provided documentation indicating work has been conducted. A field inspection will be conducted to evaluate compliance with COGCC standards.

2 ☒ CA# 110907

Corrective Action: Perform reclamation in accordance to COGCC 1000 series reclamation rules at well and access road. Ensure temporary stabilization controls are in place until more permanent vegetative stabilization has established. Reclamation activities shall be completed no later than 7/31/2017.

Date: 07/31/2017

Response: CA COMPLETED

Date of Completion: 11/22/2017

Operator Comment: Road base has been removed and the gully has been repaired. Top soil and compost has been hauled in, the area was graded ripped and cross-ripped on November 17, 2017. This location was seeded, mulched and crimped on November 22, 2017

COGCC Decision: Approved pending re-inspection

COGCC Representative: "Approved pending re-inspection" of the FIR resolution acknowledges that the Oil and Gas Conservation Commission has received the notice. It is not an acknowledgement that the corrective action has been passed. Operator has not provided documentation indicating work has been conducted. A field inspection will be conducted to evaluate compliance with COGCC standards.

3 ☒ CA# 110908

Corrective Action: Repair erosion and install or repair required BMPs per Rule 1002.f

Date: 07/31/2017

Response: CA COMPLETED

Date of Completion: 11/22/2017

Operator Comment: Noble repaired the erosion in the access road by removing the road base, bringing in topsoil, and regrading. The regraded areas were seeded, mulched and crimped to control erosion.

COGCC Decision: Approved pending re-inspection

COGCC Representative: "Approved pending re-inspection" of the FIR resolution acknowledges that the Oil and Gas Conservation Commission has received the notice. It is not an acknowledgement that the corrective action has been passed. Operator has not provided documentation indicating work has been conducted. A field inspection will be conducted to evaluate compliance with COGCC standards.

OPERATOR COMMENT AND SUBMITTAL

Comment:

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Tesla Dougherty

Signed:

Title: EHS Specialist

Date: 11/29/2017 2:40:56 PM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
------------------------	--------------------

401471232	FIR RESOLUTION SUBMITTED
-----------	--------------------------

Total Attach: 1 Files