

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:
401464651
Date Received:
11/21/2017

FIR RESOLUTION FORM

CA Summary:

1 of 1 CAs from the FIR responded to on this Form

1 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 36200
Name of Operator: GRYNBERG* JACK DBA GRYNBERG PETROLEUM CO
Address: 3600 S. YOSEMITE ST - STE 900
City: DENVER State: CO Zip: 80237-1830

Contact Name and Telephone:
Name:
Phone: () Fax: ()
Email:

Additional Operator Contact:

Contact Name	Phone	Email
Griggs, Mary	303-912-8292	mgriggs@sierra-hamilton.com
Andrews, Doug		doug.andrews@state.co.us
Griggs, Mary	303-912-8292	mgriggs@sierra-hamilton.com
		dnr_cogccenforcement@state.co.us

COGCC INSPECTION SUMMARY:

FIR Document Number: 682402931
Inspection Date: 10/24/2017 FIR Submit Date: 10/24/2017 FIR Status:

Inspected Operator Information:

Company Name: GRYNBERG* JACK DBA GRYNBERG PETROLEUM CO Company Number: 36200
Address: 3600 S. YOSEMITE ST - STE 900
City: DENVER State: CO Zip: 80237-1830

LOCATION - Location ID: 441995

Location Name: Grynberg Stateline Federal Number: 24-12-65-4 Pad County:
Qtrqr: NWN Sec: 24 Twp: 12N Range: 65W Meridian: 6
W
Latitude: 40.999203 Longitude: -104.615686

FACILITY - API Number: 05-123-00 Facility ID: 441995

Facility Name: Grynberg Stateline Federal Number: 24-12-65-4 Pad
Qtrqr: NWN Sec: 24 Twp: 12N Range: 65W Meridian: 6
W
Latitude: 40.999203 Longitude: -104.615686

CORRECTIVE ACTIONS:

1 CA# 107069

Corrective Action:

Date: 10/12/2017

Operator shall install stormwater and erosion control BMPs prior to, or at, the start of construction; therefore, the corrective action date is based off the Form 42 start of construction date.

Response: CA COMPLETED

Date of Completion: 11/06/2017

Operator Comment: Corrective action was completed in stages and is ongoing:
11/1/17 - Water truck for location as an interim action to retain fine sediment. The water truck is still in use to keep fine sediment from blowing.
11/2/17 - Sediment traps and check dams were installed.
11/6/17 - Hydromulch with a NRCS approved seed mixture was applied to the cut slopes, fill slope, and cut ditches.
11/17/17 - "As-Built" survey was generated, which shows the current disturbed area, and the proposed area for interim reclamation.

COGCC Decision: Approved pending re-inspection

COGCC Representative: This is an acknowledgement that the document was received. COGCC staff will perform an on-the-ground inspection at a future date to determine whether the installed BMPs and repairs appear to be in compliance with Rule 1002.f.

OPERATOR COMMENT AND SUBMITTAL

Comment: The well pad surface will have additional treatment to stabilize the surface. A magnesium chloride solution for use on the well pad surface and access road has been approved by the surface owner. More permanent treatment of the well pad surface is pending.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Mary C Griggs

Signed: _____

Title: Director for Receiver

Date: 11/21/2017 12:42:25 PM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
401464651	FIR RESOLUTION SUBMITTED
401464725	Survey - As Built

Total Attach: 2 Files