

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

401493217

Date Received:

12/21/2017

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

1 of 1 CAs from the FIR responded to on this Form

1 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 46685

Name of Operator: KINDER MORGAN CO2 CO LP

Address: 1001 LOUISIANA ST SUITE 1000

City: HOUSTON State: TX Zip: 77002

Contact Name and Telephone:

Name: _____

Phone: () _____ Fax: () _____

Email: _____

Additional Operator Contact:

Contact Name	Phone	Email
<u>Millican, Chris</u>		<u>chris_millican@kindermorgan.com</u>
<u>Swift, Barry</u>	<u>970-882-5545</u>	<u>barry_swift@kindermorgan.com</u>
<u>Hannigan, Michael</u>	<u>(970) 882-5532</u>	<u>michael_hannigan@kindermorgan.com</u>

COGCC INSPECTION SUMMARY:

FIR Document Number: 680602290

Inspection Date: 11/16/2017

FIR Submit Date: 12/12/2017

FIR Status: _____

Inspected Operator Information:

Company Name: KINDER MORGAN CO2 CO LP

Company Number: 46685

Address: 1001 LOUISIANA ST SUITE 1000

City: HOUSTON State: TX Zip: 77002

LOCATION - Location ID: 432954

Location Name: GOODMAN POINT (GP) Number: 26 County: MONTEZUMA

Qtrqtr: NESE Sec: 7 Twp: 36N Range: 17W Meridian: N

Latitude: 37.392050 Longitude: -108.755470

FACILITY - API Number: 05-083- -00 Facility ID: 432955

Facility Name: GOODMAN POINT (GP) Number: 26

Qtrqtr: NESE Sec: 7 Twp: 36N Range: 17W Meridian: N

Latitude: 37.392050 Longitude: -108.755470

CORRECTIVE ACTIONS:

1 CA# 113323

Corrective Action: Evaluate stormwater flow patterns along the western edge of the working area and apply controls as needed to prevent concentrated flows from exiting the well pad and eroding adjacent cropland. Additionally, maintain/replace wattle at entrance to the well pad.

Date: 01/19/2018

Response: CA COMPLETED

Date of Completion: 12/19/2017

Kinder Morgan installed a more robust stormwater drainage pattern on the GP-26 well pad and access road. The

Operator Comment: grade of the western side the location was raised to funnel stormwater to newly installed diversion ditches along the northern and southern edges of the well pad. Newly constructed diversion ditches convey stormwater runoff to a series of rock check dams and rock armoring before discharging into county road bar ditch. All new disturbance within the stormwater diversion ditches have been seeded and mulched. Corrective Action has been successfully completed and location is ready for re-inspection.

COGCC Decision: _____

COGCC
Representative:

OPERATOR COMMENT AND SUBMITTAL

Comment:

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Chris Lopez

Signed: _____

Title: EHS Specialist

Date: 12/21/2017 8:47:10 AM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
------------------------	--------------------

401493245	Corrective Action Photo Evidence
-----------	----------------------------------

Total Attach: 1 Files