

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:
401477140
Date Received:
12/05/2017

FIR RESOLUTION FORM

CA Summary:
4 of 4 CAs from the FIR responded to on this Form
4 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 39560
Name of Operator: TOP OPERATING COMPANY FDBA MURRAY J HERRING LTD
Address: 3609 S WADSWORTH BLVD STE 340
City: LAKEWOOD State: CO Zip: 80235
Contact Name and Telephone:
Name:
Phone: () Fax: ()
Email:

Additional Operator Contact:
Contact Name: Paul Herring
Phone: 2143363981
Email: paul.herring@topoperating.com

COGCC INSPECTION SUMMARY:

FIR Document Number: 677400005
Inspection Date: 11/03/2017 FIR Submit Date: 11/03/2017 FIR Status:

Inspected Operator Information:

Company Name: TOP OPERATING COMPANY FDBA MURRAY J HERRING LTD
Company Number: 39560
Address: 3609 S WADSWORTH BLVD STE 340
City: LAKEWOOD State: CO Zip: 80235

LOCATION - Location ID: 317954

Location Name: COUNTER-62N66W Number: 30NENE County:
Qtrqr: NENE Sec: 30 Twp: 2N Range: 66W Meridian: 6
Latitude: 40.114618 Longitude: -104.813031

FACILITY - API Number: 05-123-00 Facility ID: 317954

Facility Name: COUNTER-62N66W Number: 30NENE
Qtrqr: NENE Sec: 30 Twp: 2N Range: 66W Meridian: 6
Latitude: 40.114618 Longitude: -104.813031

CORRECTIVE ACTIIONS:

1 CA# 109763
Corrective Action: Repair or install berms or other secondary containment devices per Rule 906.d.(1). Date: 11/30/2017
Response: CA COMPLETED Date of Completion: 11/28/2017
Operator Comment: Berms have been reinstalled

COGCC Representative: BERMS REPAIRED

2 CA# 109764

Corrective Action: Repair or install berms or other secondary containment devices per Rule 906.d.(1).

Date: 12/03/2017

Response: CA COMPLETED

Date of Completion: 11/28/2017

Operator Comment: Berms have been reinstalled

COGCC Decision: Approved

COGCC Representative: BERMS HAVE BEEN REPAIRED

3 CA# 109765

Corrective Action: Control and contain spills/releases and clean up per Rule 906.a. Contact COGCC EPS staff.

Date: 12/03/2017

Response: CA COMPLETED

Date of Completion: 11/28/2017

Operator Comment: Stained soil removed around well head and well head cleaned up.

COGCC Decision: Approved

COGCC Representative: STAINED SOIL CLEANED UP

4 CA# 109766

Corrective Action: Comply with Rule 603.f .

Date: 12/03/2017

Response: CA COMPLETED

Date of Completion: 12/05/2017

Operator Comment: The equipment on site is allowed based on an agreement to build and maintain the bridge across the ditch on this land. Agreement letter attached.

COGCC Decision: Approved

COGCC Representative: BRIDGE IS GOOD CONDITION

OPERATOR COMMENT AND SUBMITTAL

Comment:

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Paul

Signed:

Title: Herring

Date: 12/5/2017 4:29:51 PM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

Document Number	Description
401477140	FIR RESOLUTION SUBMITTED
401477165	Correspondance from land owner

Total Attach: 2 Files