

Location Name: TEP API 045-06799

12/18/2017



Pig receiver at valve can looking north



Runoff area looking north from spil point

TEP 045-06799

Inspection 12/18/17



Runoff looking south towards spill point



Spill erosion around valve can