

State of Colorado  
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:  
401483790  
Date Received:  
12/12/2017

FIR RESOLUTION FORM

CA Summary:

2 of 2 CAs from the FIR responded to on this Form

2 CA Completed  
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 24320  
Name of Operator: DIAMOND OPERATING, INC.  
Address: 6666 GUNPARK DR STE #200  
City: BOULDER State: CO Zip: 80301

Contact Name and Telephone:  
Name:  
Phone: ( ) Fax: ( )  
Email:

Additional Operator Contact:

Contact Name Phone Email  
Dave Peterson 303-494-4420 davep@flatironenergy.com

COGCC INSPECTION SUMMARY:

FIR Document Number: 684904675  
Inspection Date: 11/03/2017 FIR Submit Date: 11/03/2017 FIR Status:

Inspected Operator Information:

Company Name: DIAMOND OPERATING, INC. Company Number: 24320  
Address: 6666 GUNPARK DR STE #200  
City: BOULDER State: CO Zip: 80301

LOCATION - Location ID: 305616

Location Name: DUNBAR-69N61W Number: 4SESW County: WELD  
Qtrqr: SESW Sec: 4 Twp: 9N Range: 61W Meridian: 6  
Latitude: 40.773326 Longitude: -104.213833

FACILITY - API Number: 05-123-00 Facility ID: 281705

Facility Name: DUNBAR Number: 1  
Qtrqr: SESW Sec: 4 Twp: 9N Range: 61W Meridian: 6  
Latitude: 40.773326 Longitude: -104.213833

CORRECTIVE ACTIONS:

1 CA# 109433

Corrective Action: Comply with Rule 603.f. Date: 02/05/2018

Response: CA COMPLETED Date of Completion: 11/24/2017

Operator Comment: Operator spoke with Conor Pesika and requested a six month time extension to comply with Rule 603.f. and the removal of the heater-treater that is not in service. It is anticipated that early next summer this heater treater will be used to replace the heater treater at the Dunbar that is currently in operation.

COGCC Decision: Approved via an AMI

COGCC  
Representative:

2  CA# 109434

Corrective Action: Install or repair required BMPs per Rule 1002.f.

Date: 12/04/2017

Response: CA COMPLETED

Date of Completion: 12/12/2017

Operator Comment: Areas of stormwater erosion along the exterior of the tank battery site have been repaired and hay barriers have been placed along the primary areas of flow to mitigate future erosion.

COGCC Decision: Approved via an AMI

COGCC  
Representative:

#### OPERATOR COMMENT AND SUBMITTAL

Comment: Requesting final approval of FIRR 684904675.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Dave Peterson

Signed: \_\_\_\_\_

Title: President

Date: 12/12/2017 2:54:53 PM

#### **ATTACHMENT LIST**

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
401483790	FIR RESOLUTION SUBMITTED
401483825	Photo of south side of tank battery site
401483826	Photo of west site of tank battery site

Total Attach: 3 Files