

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

12/20/2017

Submitted Date:

12/30/2017

Document Number:

671000814**FIELD INSPECTION FORM**

Loc ID 418695 Inspector Name: DURAN, JOHN On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_

**Operator Information:**OGCC Operator Number: 44390Name of Operator: JAVERNICK OILAddress: 3040 E MAINCity: CANON CITY State: CO Zip: 81212**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**5 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
Javernick, James	719-275-3040/719-671-3787	javernick1@gmail.com	<a href="#">All Inspections</a>
Mehennett, Tom	(719) 275-3040/(505) 330-1328	tbm3040@gmail.com	<a href="#">All Inspections</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
418701	WELL	WO	10/12/2012	LO	043-06196	CHANDLER CREEK 24-32	TA

**General Comment:**

**Location**Overall Good: ☐

Emergency Contact Number:

Comment: Corrective Action: Date: Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Equipment:**

Type: Deadman # & Marked	# 0		corrective date
Comment:			
Corrective Action:		Date:	
Type: Ancillary equipment	# 1		
Comment: Wellhead			
Corrective Action:		Date:	

**Venting:**

Yes/No			
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type			
Comment:			
Corrective Action:		Date:	



**Reclamation - Storm Water - Pit****Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**COGCC Comments**

Comment	User	Date
On site at 7:30 am. A smaller diameter plug (4 inches) was attached to cable and lowered to a depth of 376 ft (cable + wooden plug). Then 2 sxs of cement was put on top of plug. Crew will put remaining 8 sxs on top this afternoon. Off site 8:12 am.	duranj	12/20/2017