

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

401501209

Date Received:

01/03/2018

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

1 of 3 CAs from the FIR responded to on this Form

1 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10000

Name of Operator: BP AMERICA PRODUCTION COMPANY

Address: 380 AIRPORT RD

City: DURANGO State: CO Zip: 81303

Contact Name and Telephone:

Name: _____

Phone: () _____ Fax: () _____

Email: _____

Additional Operator Contact:

| Contact Name | Phone | Email |
|-------------------------|---------------------|------------------------------------|
| <u>Labowskie, Steve</u> | | <u>steve.labowskie@state.co.us</u> |
| <u>Hughes, Jim</u> | | <u>jimo.hughes@state.co.us</u> |
| <u>Beebe, Sabre</u> | <u>970-375-7530</u> | <u>Sabre.Beebe@bp.com</u> |
| <u>Inspections, All</u> | | <u>SanJuanCOGCC@bp.com</u> |

COGCC INSPECTION SUMMARY:

FIR Document Number: 685303553

Inspection Date: 07/13/2017

FIR Submit Date: 07/17/2017

FIR Status: _____

Inspected Operator Information:

Company Name: BP AMERICA PRODUCTION COMPANY

Company Number: 10000

Address: 380 AIRPORT RD

City: DURANGO State: CO Zip: 81303

LOCATION - Location ID: 306945

Location Name: ARCHULETA DIX G.U.-M34N6W Number: 9SENE County: LA PLATA

Qtrqr: SENE Sec: 9 Twp: 34N Range: 6W Meridian: N

Latitude: 37.229128 Longitude: -107.527561

FACILITY - API Number: 05-067- -00 Facility ID: 281473

Facility Name: ARCHULETA-DIX Number: 2

Qtrqr: SENE Sec: 9 Twp: 34N Range: 6W Meridian: N

Latitude: 37.229128 Longitude: -107.527561

CORRECTIVE ACTIONS:

3 CA# 86443

Corrective Action: Work with landowner to comply with Surface Use Agreement and remove materials and storage to move location in compliance with Rule 1003 or obtain waiver.

Date: 10/17/2017

Response: CA COMPLETED

Date of Completion: 12/29/2017

Operator: Land owner has removed all belonging that were encroaching upon the well pad and in the interim reclamation.
Comment: Fencing has been installed between landowner "bone yard" and BP operations to prevent future encroachment upon BP Operations well pad. See attached photo of work completed.

COGCC Decision: _____

COGCC
Representative:

OPERATOR COMMENT AND SUBMITTAL

Comment: Land owner has removed all belonging that were encroaching upon the well pad and in the interim reclamation. Fencing has been installed between landowner "bone yard" and BP operations to prevent future encroachment upon BP Operations well pad. See attached photo of work completed. While on location BP personnel noted stained soils which were cleaned up and deposited into the soil box at the BP office for remediation at IEI

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Sabre Beebe

Signed: _____

Title: Construction Specialist

Date: 1/3/2018 12:55:46 PM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

| <u>Document Number</u> | <u>Description</u> |
|------------------------|--------------------|
|------------------------|--------------------|

| | |
|-----------|------------------------|
| 401501218 | Work Completion photos |
|-----------|------------------------|

Total Attach: 1 Files