

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:
401499142
Date Received:
01/02/2018

FIR RESOLUTION FORM

CA Summary:

1 of 1 CAs from the FIR responded to on this Form

1 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10000
Name of Operator: BP AMERICA PRODUCTION COMPANY
Address: 380 AIRPORT RD
City: DURANGO State: CO Zip: 81303
Contact Name and Telephone:
Name: _____
Phone: () _____ Fax: () _____
Email: _____

Additional Operator Contact:

Contact Name	Phone	Email
<u>Beebe, Sabre</u>	<u>970-375-7530</u>	<u>Sabre.Beebe@bp.com</u>
<u>Fischer, Alex</u>		<u>alex.fischer@state.co.us</u>
<u>Leonard, Mike</u>		<u>mike.leonard@state.co.us</u>
<u>Inspections, All</u>		<u>SanJuanCOGCC@bp.com</u>

COGCC INSPECTION SUMMARY:

FIR Document Number: 674901976
Inspection Date: 11/15/2017 FIR Submit Date: 11/17/2017 FIR Status: _____

Inspected Operator Information:

Company Name: BP AMERICA PRODUCTION COMPANY Company Number: 10000
Address: 380 AIRPORT RD
City: DURANGO State: CO Zip: 81303

LOCATION - Location ID: 326343

Location Name: SEMLER GAS UNIT A- N33N8W Number: 1SWNW County: LA PLATA
Qtrqtr: SWN Sec: 1 Twp: 33N Range: 8W Meridian: N
Latitude: 37.135349 Longitude: -107.673358

FACILITY - API Number: 05-067-00 Facility ID: 216267

Facility Name: SEMLER A Number: 1
Qtrqtr: SWN Sec: 1 Twp: 33N Range: 8W Meridian: N
Latitude: 37.135349 Longitude: -107.673358

CORRECTIVE ACTIONS:

1 ☒ CA# 111041

Corrective Action: Install sign to comply with Rule 210.b

Date: 12/18/2017

Response: CA COMPLETED

Date of Completion: 12/14/2017

Operator Comment: A new well sign has been placed on location and the old sign with base has been removed from location. See attached photos

COGCC Decision: Approved via an AMI

COGCC Representative:

OPERATOR COMMENT AND SUBMITTAL

Comment: A new sign has been installed on the Semler A 1 well and the old sign with base has been removed see photos attached. In addition while installing the new sign erosion near entrance of well pad and along the road was observed by BP Personnel. This erosion has been addressed with installation of rock run down and the pot holes in the road repaired. Please see attached documentation of all work completed.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Sabre Beebe

Signed: _____

Title: Construction Specialist

Date: 1/2/2018 7:23:01 AM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
401499142	FIR RESOLUTION SUBMITTED
401499151	Sign replacement photo
401499152	Stormwater repairs photos

Total Attach: 3 Files