

Interim Reclamation Inspection

January 9, 2018

Operator: RED HAWK PETROLEUM LLC - #10503

Location ID: 431634

Inspection Document #: 682403190

Weld County, CO

NWSW Section 2 T7N R60W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos
Location: Buchner #2-2H
Location ID: 431634



Photo 1. Aerial imagery taken from the COGCC GISOnline database from 2013 illustrating the Buchner location that was constructed.

Inspection Photos
Location: Buchner #2-2H
Location ID: 431634



Photo 2. Aerial imagery taken from the COGCC GISOnline database from 2015 illustrating the Buchner location that was constructed in 2013. Operator has failed to perform interim reclamation per Rule 1003.b.

Inspection Photos
Location: Buchner #2-2H
Location ID: 431634



Photo 3. Photo taken from the eastern location on top of a stockpile, facing South. Soil stockpile appears to be stabilized and protected per Rule 1002.c.



Photo 4. Photo taken from the eastern location on top of a stockpile, facing North. See comments under Photo 3.

Inspection Photos
Location: Buchner #2-2H
Location ID: 431634



Photo 5. Photo taken from the eastern location on top of a stockpile, facing Southwest. Operator has failed to perform interim reclamation per Rule 1003.b. to reduce disturbance areas only reasonably needed for production operations.



Photo 6. Photo taken from the eastern location on top of a stockpile, facing West. See comments under Photo 5.

Inspection Photos
Location: Buchner #2-2H
Location ID: 431634



Photo 7. Photo taken from the eastern location on top of a stockpile, facing Northwest. See comments under Photo 5.



Photo 8. Photo taken of the well sign at location.