

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

401507489

Date Received:

01/12/2018

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

3 of 3 CAs from the FIR responded to on this Form

3 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 46290

Name of Operator: K P KAUFFMAN COMPANY INC

Address: 1675 BROADWAY, STE 2800

City: DENVER State: CO Zip: 80202

Contact Name and Telephone:

Name: _____

Phone: () _____ Fax: () _____

Email: _____

Additional Operator Contact:

Contact Name

Susana Lara-Mesa

Phone

303-825-4822

Email

slaramesa@kpk.com

COGCC INSPECTION SUMMARY:

FIR Document Number: 677400258

Inspection Date: 12/19/2017

FIR Submit Date: 12/19/2017

FIR Status: _____

Inspected Operator Information:

Company Name: K P KAUFFMAN COMPANY INC

Company Number: 46290

Address: 1675 BROADWAY, STE 2800

City: DENVER State: CO Zip: 80202

LOCATION - Location ID: 319272

Location Name: RINGSBY-61N65W Number: 12CNW County: _____

Qtrqr: CNW Sec: 12 Twp: 1N Range: 65W Meridian: 6

Latitude: 40.069525 Longitude: -104.616899

FACILITY - API Number: 05-123- -00 Facility ID: 319272

Facility Name: RINGSBY-61N65W Number: 12CNW

Qtrqr: CNW Sec: 12 Twp: 1N Range: 65W Meridian: 6

Latitude: 40.069525 Longitude: -104.616899

CORRECTIVE ACTIONS:

1 CA# 113484

Corrective Action: Location is within an exception zone, repair or install berms or other secondary containment devices per Rule 604.c.(3)B.

Date: 01/03/2018

Response: CA COMPLETED

Date of Completion: 01/08/2018

Operator Comment: 25 bbl capacity concrete vault berms have repaired. See attached picture.

COGCC Decision: _____

COGCC
Representative:

2 CA# 113485

Corrective Action: Location is within an exception zone, repair or install berms or other secondary containment devices per Rule 604.c.(3)B.

Date: 01/03/2018

Response: CA COMPLETED

Date of Completion: 01/08/2018

Operator
Comment: Berms have repaired. See attached picture.

COGCC Decision: _____

COGCC
Representative:

3 CA# 113486

Corrective Action: Location is within an exception zone, repair or install berms or other secondary containment devices per Rule 604.c.(3)B.

Date: 01/03/2018

Response: CA COMPLETED

Date of Completion: 01/08/2018

Operator
Comment: Berms have repaired. See attached picture.

COGCC Decision: _____

COGCC
Representative:

OPERATOR COMMENT AND SUBMITTAL

Comment:

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Susana Lara-Mesa

Signed: _____

Title: VP of Engineering

Date: 1/12/2018 11:43:28 AM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
------------------------	--------------------

401507625	Repaired berms PIC1
401507627	Repaired berms PIC2
401507633	Repaired berms PIC3

Total Attach: 3 Files