

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
 Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

401507261

Date Received:

01/11/2018

Spill report taken by:

ALLISON, RICK

Spill/Release Point ID:

453636

SPILL/RELEASE REPORT (SUPPLEMENTAL)

This form is to be submitted by the party responsible for the oil and gas spill or release. Refer to COGCC Rule 906.b. for reporting requirements of spills or releases of E&P Waste or produced fluids. Submit a Site Investigation and Remediation Workplan (Form 27) when requested by the Director.

OPERATOR INFORMATION

Name of Operator: <u>PDC ENERGY INC</u>	Operator No: <u>69175</u>	Phone Numbers
Address: <u>1775 SHERMAN STREET - STE 3000</u>		Phone: <u>(970) 506-9272</u>
City: <u>DENVER</u>	State: <u>CO</u>	Zip: <u>80203</u>
Contact Person: <u>Zack Liesenfeld</u>		Mobile: <u>(970) 373-6581</u>
		Email: <u>Zack.Liesenfeld@pdce.com</u>

INITIAL SPILL/RELEASE REPORT

Initial Spill/Release Report Doc# 401504549

Initial Report Date: 01/05/2018 Date of Discovery: 01/04/2018 Spill Type: Recent Spill

Spill/Release Point Location:

Location of Spill/Release: QTRQTR NESE SEC 8 TWP 5N RNG 63W MERIDIAN 6

Latitude: 40.410209 Longitude: -104.455700

Municipality (if within municipal boundaries): _____ County: WELD

Reference Location:

Facility Type: TANK BATTERY☐ Facility/Location ID No _____☒ No Existing Facility or Location ID No.☐ Well API No. (Only if the reference facility is well) 05- -

Fluid(s) Spilled/Released (please answer Yes/No):

Was one (1) barrel or more spilled outside of berms or secondary containment? Yes

Secondary containment, including walls & floor regardless of construction material, must be sufficiently impervious to contain any discharge from primary containment until cleanup occurs.

Were Five (5) barrels or more spilled? No

Estimated Total Spill Volume: use same ranges as others for values

Estimated Oil Spill Volume(bbl): >=1 and <5Estimated Condensate Spill Volume(bbl): 0Estimated Flow Back Fluid Spill Volume(bbl): 0Estimated Produced Water Spill Volume(bbl): 0Estimated Other E&P Waste Spill Volume(bbl): 0Estimated Drilling Fluid Spill Volume(bbl): 0

Specify: _____

Land Use:

Current Land Use: NON-CROP LAND

Other(Specify): _____

Weather Condition: Cool and OvercastSurface Owner: STATE

Other(Specify): _____

Check if impacted or threatened by spill/Release (please answer Yes/No to all that apply):

Waters of the State ☐ Residence/Occupied Structure ☐ Livestock ☐ Public Byway ☐ Surface Water Supply Area ☐

As defined in COGCC 100-Series Rules

Describe what is known about the spill/release event (what happened -- including how it was stopped, contained, and recovered):

On January 4th, 2018 PDC Energy learned of a crude oil release on the State 5519 8-34, 43, 33-8, 8A. Upon arrival to location the pumper discovered more than 1 but less than 5 barrels of crude oil had been released outside of containment. The well was immediately shut in and current recovery efforts are mitigating soil impacts.

List Agencies and Other Parties Notified:

OTHER NOTIFICATIONS

Date	Agency/Party	Contact	Phone	Response
1/4/2018	COGCC	Rick	-	Via Email
1/4/2018	Landowner	State Land Board	-	Via Phone Call
1/4/2018	Weld County	Roy Rudisill	-	Via Email

SPILL/RELEASE DETAIL REPORTS

#1	Supplemental Report Date: 01/09/2018		
FLUIDS	BBL's SPILLED	BBL's RECOVERED	Unknown
OIL	1	0	<input type="checkbox"/>
CONDENSATE	0	0	<input type="checkbox"/>
PRODUCED WATER	0	0	<input type="checkbox"/>
DRILLING FLUID	0	0	<input type="checkbox"/>
FLOW BACK FLUID	0	0	<input type="checkbox"/>
OTHER E&P WASTE	0	0	<input type="checkbox"/>

specify: _____

Was spill/release completely contained within berms or secondary containment? NO Was an Emergency Pit constructed? NO

Secondary containment, including walls & floor regardless of construction material, must be sufficiently impervious to contain any discharge from primary containment until cleanup occurs.

A Form 15 Pit Report shall be submitted within 30 calendar days after the construction of an emergency pit

Impacted Media (Check all that apply) ☒ Soil ☐ Groundwater ☐ Surface Water ☐ Dry Drainage Feature

Surface Area Impacted: Length of Impact (feet): 87 Width of Impact (feet): 26

Depth of Impact (feet BGS): 1 Depth of Impact (inches BGS): _____

How was extent determined?

On January 4, 2017, approximately 1 barrel of oil was released from a pressure relief valve on the separator at the State 5519 8-34, 43, 33-8, 8A production facility. Following the discovery of the release, the wellhead was shut-in and mitigation efforts were initiated. Approximately 20 cubic yards of impacted material were removed and transported to the North Weld Landfill in Ault, Colorado for disposal under PDC waste manifests. Seven (7) soil samples (SS01 - SS07) were collected between 6 inches and 1 foot below ground surface (bgs). The soil samples were submitted to Summit Scientific Laboratories in Golden, Colorado for analysis of benzene, toluene, ethylbenzene, total xylenes (BTEX), naphthalene, total petroleum hydrocarbons (TPH) - gasoline range organics (GRO) by United States Environmental Protection Agency (USEPA) Method 8260B, and TPH - diesel range organics (DRO) by USEPA Method 8015. Analytical results indicated that constituent concentrations were below the applicable COGCC Table 910-1 standards in all seven soil samples. Based on the analytical results described herein, PDC is requesting a No Further Action (NFA) designation for this release. The release area and sample locations are illustrated on Figure 2 and the soil analytical results are summarized in Table 1. The laboratory report is included in Attachment A.

Soil/Geology Description:

Valent sand, 3 to 9 percent slopes.

Depth to Groundwater (feet BGS) 38 Number Water Wells within 1/2 mile radius: 0

If less than 1 mile, distance in feet to nearest Water Well _____ None ☒ Surface Water _____ None ☒

Wetlands _____ None ☒Springs _____ None ☒Livestock 1200 None ☐Occupied Building _____ None ☒

Additional Spill Details Not Provided Above:

CORRECTIVE ACTIONS#1 Supplemental Report Date: 01/09/2017Cause of Spill (Check all that apply) ☐ Human Error ☒ Equipment Failure ☐ Historical-Unknown☐ Other (specify) _____

Describe Incident & Root Cause (include specific equipment and point of failure)

On January 4, 2018, approximately 1 barrel of oil was released from the pressure relief valve on the separator due to an unforeseen malfunction of the high low controller.

Describe measures taken to prevent the problem(s) from reoccurring:

The pressure relief valve was replaced, routine pressure and integrity tests will continue along with annual inspections of the high low controller.

Volume of Soil Excavated (cubic yards): 20Disposition of Excavated Soil (attach documentation) ☒ Offsite Disposal ☐ Onsite Treatment☐ Other (specify) _____Volume of Impacted Ground Water Removed (bbls): 0Volume of Impacted Surface Water Removed (bbls): 0**REQUEST FOR CLOSURE****Spill/Release Reports should be closed when impacts have been remediated or when further investigation and corrective actions will take place under an approved Form 27.**Basis for Closure: ☒ Corrective Actions Completed (documentation attached)☐ Work proceeding under an approved Form 27

Form 27 Remediation Project No: _____

OPERATOR COMMENTS:

I hereby certify all statements made in this form are to the best of my knowledge true, correct, and complete.

Signed: _____ Print Name: Zack LiesenfeldTitle: EHS Professional Date: 01/11/2018 Email: Zack.Liesenfeld@pdce.com**COA Type****Description****Attachment Check List****Att Doc Num****Name**

401507261	SPILL/RELEASE REPORT(SUPPLEMENTAL)
401509522	TOPOGRAPHIC MAP
401509546	SITE MAP
401509558	ANALYTICAL RESULTS

401515921	FORM 19 SUBMITTED
-----------	-------------------

Total Attach: 5 Files

General Comments

<u>User Group</u>	<u>Comment</u>	<u>Comment Date</u>
Environmental	Based on the information presented, it appears that no further action is necessary at this time and the COGCC approves the closure request. However, should future conditions at the site indicate contaminant concentrations in soils exceeding COGCC standards or if ground water is found to be impacted, then further investigation and/or remediation activities may be required. In addition, the surface area disturbed by the remediation activity shall be reclaimed in accordance with the 1000 Series Reclamation Rules.	01/16/2018

Total: 1 comment(s)