

State of Colorado  
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:  
401507489  
Date Received:  
01/12/2018

FIR RESOLUTION FORM

CA Summary:  
3 of 3 CAs from the FIR responded to on this Form  
3 CA Completed  
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 46290  
Name of Operator: K P KAUFFMAN COMPANY INC  
Address: 1675 BROADWAY, STE 2800  
City: DENVER State: CO Zip: 80202  
Contact Name and Telephone:  
Name:  
Phone: ( ) Fax: ( )  
Email:

Additional Operator Contact:

Contact Name Phone Email  
Susana Lara-Mesa 303-825-4822 slaramesa@kpk.com

COGCC INSPECTION SUMMARY:

FIR Document Number: 677400258  
Inspection Date: 12/19/2017 FIR Submit Date: 12/19/2017 FIR Status:

Inspected Operator Information:

Company Name: K P KAUFFMAN COMPANY INC Company Number: 46290  
Address: 1675 BROADWAY, STE 2800  
City: DENVER State: CO Zip: 80202

LOCATION - Location ID: 319272

Location Name: RINGSBY-61N65W Number: 12CNW County:  
Qtrqtr: CNW Sec: 12 Twp: 1N Range: 65W Meridian: 6  
Latitude: 40.069525 Longitude: -104.616899

FACILITY - API Number: 05-123-00 Facility ID: 319272

Facility Name: RINGSBY-61N65W Number: 12CNW  
Qtrqtr: CNW Sec: 12 Twp: 1N Range: 65W Meridian: 6  
Latitude: 40.069525 Longitude: -104.616899

CORRECTIVE ACTIONS:

1  CA# 113484

Corrective Action: Location is within an exception zone, repair or install berms or other secondary containment devices per Rule 604.c.(3)B. Date: 01/03/2018

Response: CA COMPLETED Date of Completion: 01/08/2018

Operator Comment: 25 bbl capacity concrete vault berms have repaired. See attached picture.

COGCC Decision: Approved

COGCC Representative: pictures look good

**2**  CA# 113485

Corrective Action: Location is within an exception zone, repair or install berms or other secondary containment devices per Rule 604.c.(3)B.

Date: 01/03/2018

Response: CA COMPLETED

Date of Completion: 01/08/2018

Operator Comment: Berms have repaired. See attached picture.

COGCC Decision: Approved

COGCC Representative: pictures look good

**3**  CA# 113486

Corrective Action: Location is within an exception zone, repair or install berms or other secondary containment devices per Rule 604.c.(3)B.

Date: 01/03/2018

Response: CA COMPLETED

Date of Completion: 01/08/2018

Operator Comment: Berms have repaired. See attached picture.

COGCC Decision: Approved

COGCC Representative: pictures look good

#### OPERATOR COMMENT AND SUBMITTAL

Comment:

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Susana Lara-Mesa

Signed: \_\_\_\_\_

Title: VP of Engineering

Date: 1/12/2018 11:43:28 AM

#### ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<b>Document Number</b>	<b>Description</b>
401507489	FIR RESOLUTION SUBMITTED
401507625	Repaired berms PIC1
401507627	Repaired berms PIC2
401507633	Repaired berms PIC3

Total Attach: 4 Files