

State of Colorado  
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:  
401501209  
Date Received:  
01/03/2018

FIR RESOLUTION FORM

CA Summary:  
1 of 3 CAs from the FIR responded to on this Form  
1 CA Completed  
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10000  
Name of Operator: BP AMERICA PRODUCTION COMPANY  
Address: 380 AIRPORT RD  
City: DURANGO State: CO Zip: 81303  
Contact Name and Telephone:  
Name:  
Phone: ( ) Fax: ( )  
Email:

Additional Operator Contact:

Contact Name	Phone	Email
Labowskie, Steve		steve.labowskie@state.co.us
Hughes, Jim		jimo.hughes@state.co.us
Beebe, Sabre	970-375-7530	Sabre.Beebe@bp.com
Inspections, All		SanJuanCOGCC@bp.com

COGCC INSPECTION SUMMARY:

FIR Document Number: 685303553  
Inspection Date: 07/13/2017 FIR Submit Date: 07/17/2017 FIR Status:

Inspected Operator Information:

Company Name: BP AMERICA PRODUCTION COMPANY Company Number: 10000  
Address: 380 AIRPORT RD  
City: DURANGO State: CO Zip: 81303

LOCATION - Location ID: 306945

Location Name: ARCHULETA DIX G.U.- M34N6W Number: 9SENE County: LA PLATA  
Qtrqtr: SENE Sec: 9 Twp: 34N Range: 6W Meridian: N  
Latitude: 37.229128 Longitude: -107.527561

FACILITY - API Number: 05-067-00 Facility ID: 281473

Facility Name: ARCHULETA-DIX Number: 2  
Qtrqtr: SENE Sec: 9 Twp: 34N Range: 6W Meridian: N  
Latitude: 37.229128 Longitude: -107.527561

CORRECTIVE ACTIIONS:

3  CA# 86443

Corrective Action: Work with landowner to comply with Surface Use Agreement and remove materials and storage to move location in compliance with Rule 1003 or obtain waiver.

Date: 10/17/2017

Response: CA COMPLETED

Date of Completion: 12/29/2017

Operator Comment: Land owner has removed all belonging that were encroaching upon the well pad and in the interim reclamation. Fencing has been installed between landowner "bone yard" and BP operations to prevent future encroachment upon BP Operations well pad. See attached photo of work completed.

COGCC Decision: Approved

COGCC Representative: Approved using photo documentation provided by operator.

**OPERATOR COMMENT AND SUBMITTAL**

Comment: Land owner has removed all belonging that were encroaching upon the well pad and in the interim reclamation. Fencing has been installed between landowner "bone yard" and BP operations to prevent future encroachment upon BP Operations well pad. See attached photo of work completed. While on location BP personnel noted stained soils which were cleaned up and deposited into the soil box at the BP office for remediation at IEI

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Sabre Beebe Signed: \_\_\_\_\_

Title: Construction Specialist Date: 1/3/2018 12:55:46 PM

**ATTACHMENT LIST**

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<b><u>Document Number</u></b>	<b><u>Description</u></b>
401501209	FIR RESOLUTION SUBMITTED
401501218	Work Completion photos

Total Attach: 2 Files