

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

01/08/2018

Submitted Date:

01/09/2018

Document Number:

684904846**FIELD INSPECTION FORM**

Loc ID 440224 Inspector Name: Pesicka, Conor On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_

**Operator Information:**OGCC Operator Number: 10459Name of Operator: EXTRACTION OIL & GAS INCAddress: 370 17TH STREET SUITE 5300City: DENVER State: CO Zip: 80202**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**3 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
,		COGCCInspections@extracti onog.com	<a href="#">All Inspections inc 8 North, 7 North, XPR</a>
Adamczyk, Megan		megan.adamczyk@state.co.u s	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
440219	WELL	PR	07/01/2017	LO	123-40736	BURROUGHS SOUTH 12	PR

**General Comment:**

**Inspected Facilities**

Facility ID: 440219 Type: WELL API Number: 123-40736 Status: PR Insp. Status: PR

**Complaint**

Comment: Complaint #: 200443964, 200444165, 200444246, 200444634, 200444809

Field Inspector Assigned: C Pesicka

Well Number: 05- Location #: 440224

Inspection Document #: 684904846

Nature of complaint: Sound

If Sound GPS Coordinates of Survey Location: 40.56853, -104.64017

Inspection Observations:

An inspection of the above location was conducted with focus sound. A sound study was conducted at the above location, from 1200hr on 01/05/18 to 1300hr on 01/08/17. The complainant provided logs stating when vibration occurred at the residence. This is correlated with the sound study attached. Extraction has been contacted about conducting a sound impact study.

COGCC noise survey results indicate noise levels exceed limits in Rule 802

Corrective Action: Comply with Rule 802. For low frequency issues, obtain a low frequency impact analysis and identify control measures. (48 hr CA)

Date: 01/11/2018

**COGCC Comments**

Comment	User	Date
Sound meter's time was not set for the end of Daylights Savings Time, and all given times are one hour ahead of when they actually occurred.	pesickac	01/09/2018
Attached image is a larger version of the chart in the sound study report, to accomodate for readability of captioning.		

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401507657	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4344667">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4344667</a>
684904847	Site photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4344664">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4344664</a>
684904848	Sound Study	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4344665">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4344665</a>
684904849	Sound Study chart expanded	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4344666">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4344666</a>