

State of Colorado  
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:  
401520979  
Date Received:  
01/22/2018

FIR RESOLUTION FORM

CA Summary:

1 of 2 CAs from the FIR responded to on this Form

1 CA Completed  
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10000  
Name of Operator: BP AMERICA PRODUCTION COMPANY  
Address: 380 AIRPORT RD  
City: DURANGO State: CO Zip: 81303  
Contact Name and Telephone:  
Name:  
Phone: ( ) Fax: ( )  
Email:

Additional Operator Contact:

Contact Name	Phone	Email
<u>Inspections, All</u>		<u>SanJuanCOGCC@bp.com</u>
<u>Beebe, Sabre</u>	<u>970-375-7530</u>	<u>Sabre.Beebe@bp.com</u>
<u>Fischer, Alex</u>		<u>alex.fischer@state.co.us</u>

COGCC INSPECTION SUMMARY:

FIR Document Number: 674902010  
Inspection Date: 01/03/2018 FIR Submit Date: 01/03/2018 FIR Status:

Inspected Operator Information:

Company Name: BP AMERICA PRODUCTION COMPANY Company Number: 10000  
Address: 380 AIRPORT RD  
City: DURANGO State: CO Zip: 81303

LOCATION - Location ID: 306930

Location Name: FEDERAL 1-2-N34N8W Number: 2SENE County: LA PLATA  
Qtrqr: SENE Sec: 2 Twp: 34N Range: 8W Meridian: N  
Latitude: 37.247113 Longitude: -107.707880

FACILITY - API Number: 05-067-00 Facility ID: 279557

Facility Name: FEDERAL 01-02 Number: 2  
Qtrqr: SENE Sec: 2 Twp: 34N Range: 8W Meridian: N  
Latitude: 37.247113 Longitude: -107.707880

CORRECTIVE ACTIONS:

1 ☒ CA# 113698

Corrective Action: Repair or install berms or other secondary containment devices per Rule 605.a.4. Date: 02/05/2018

Response: CA COMPLETED Date of Completion: 01/15/2018

Operator Comment: Berm has been installed around tank to comply with Rule 605.a.4. See attached photos

COGCC Decision: Approved pending re-inspection

COGCC  
Representative:

**OPERATOR COMMENT AND SUBMITTAL**

Comment: A berm has been constructed around the partially buried tank to comply with Rule 605.a.4. In addition erosion BMP's have been installed in the erosion channel in the form of a rock run down with check dam and a diversion ditch to direct storm water to the run down to prevent future channel creation. See attached photos. All CA's and comments have been addressed on this location. Any and all stained soils have been removed from location and deposited at the Durango Office soil box for remediation as a whole at IEI in Farmington, NM.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Sabre Beebe

Signed: \_\_\_\_\_

Title: Compliance Specialist

Date: 1/22/2018 6:29:29 AM

**ATTACHMENT LIST**

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

**Document Number      Description**

401520979	FIR RESOLUTION SUBMITTED
401520980	Work completion photos

Total Attach: 2 Files