

State of Colorado  
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

401553602

Date Received:

02/23/2018

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

2 of 2 CAs from the FIR responded to on this Form

2 CA Completed  
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10000  
Name of Operator: BP AMERICA PRODUCTION COMPANY  
Address: 380 AIRPORT RD  
City: DURANGO State: CO Zip: 81303  
Contact Name and Telephone:  
Name: \_\_\_\_\_  
Phone: ( ) \_\_\_\_\_ Fax: ( ) \_\_\_\_\_  
Email: \_\_\_\_\_

Additional Operator Contact:

Contact Name	Phone	Email
-		<a href="mailto:SanJuanCOGCC@bp.com">SanJuanCOGCC@bp.com</a>
<u>Beebe, Sabre</u>		<a href="mailto:Sabre.Beebe@bp.com">Sabre.Beebe@bp.com</a>

COGCC INSPECTION SUMMARY:

FIR Document Number: 680602366  
Inspection Date: 12/13/2017 FIR Submit Date: 01/02/2018 FIR Status: \_\_\_\_\_

Inspected Operator Information:

Company Name: BP AMERICA PRODUCTION COMPANY Company Number: 10000  
Address: 380 AIRPORT RD  
City: DURANGO State: CO Zip: 81303

LOCATION - Location ID: 325769

Location Name: HELEN CRAIG GAS UNIT-M34N9W Number: 9SENW County: LA PLATA  
Qtrqr: SENW Sec: 9 Twp: 34N Range: 9W Meridian: M  
Latitude: 37.208532 Longitude: -107.833313

FACILITY - API Number: 05-067-00 Facility ID: 215355

Facility Name: HELEN CRAIG Number: 1  
Qtrqr: SENW Sec: 9 Twp: 34N Range: 9W Meridian: M  
Latitude: 37.208532 Longitude: -107.833313

CORRECTIVE ACTIIONS:

1 CA# 113672

Corrective Action: Remove pipe debris. Date: 02/09/2018

Response: CA COMPLETED Date of Completion: 02/08/2018

Operator Comment: Pipe shown in the inspection is irrigation piping belonging to the land owner. This pipe has been moved off the BP disturbance area. See attached photos.

COGCC Decision: \_\_\_\_\_

COGCC  
Representative:

**2** CA# 113673

Corrective Action: Control well site and stabilize well pad cut-slope with erosion controls. Revegetation is likely the based stabilization method. Corrective action allows for seeding during the spring 2018 seeding window.

Date: 05/01/2018

Response: CA COMPLETED

Date of Completion: 02/08/2018

Operator  
Comment:

Cut area has been seeded and a temporary fence placed around the seeded area to prevent landowner from utilizing the area for ATV recreation. See attached photos.

COGCC Decision: \_\_\_\_\_

COGCC  
Representative:

#### OPERATOR COMMENT AND SUBMITTAL

Comment: Land owner pipe has been moved off of BP disturbance cut has been reseeded and fenced off to prevent landowner ATV tracking across the area  
Concrete debris found by BP but not noted in inspection has been removed and disposed of  
See attached photos of all work completed

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Sabre Beebe

Signed: \_\_\_\_\_

Title: Compliance Specialist

Date: 2/23/2018 9:28:18 AM

### **ATTACHMENT LIST**

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
------------------------	--------------------

401553621	Closure photos
-----------	----------------

Total Attach: 1 Files