

State of Colorado  
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

401568924

Date Received:

03/09/2018

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

1 of 1 CAs from the FIR responded to on this Form

1 CA Completed  
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10133

Name of Operator: HILCORP ENERGY COMPANY

Address: P O BOX 61229

City: HOUSTON State: TX Zip: 77208

Contact Name and Telephone:

Name: \_\_\_\_\_

Phone: ( ) \_\_\_\_\_ Fax: ( ) \_\_\_\_\_

Email: \_\_\_\_\_

Additional Operator Contact:

Contact Name

Phone

Email

Shorty, Priscilla

pshorty@hilcorp.com

COGCC INSPECTION SUMMARY:

FIR Document Number: 680602491

Inspection Date: 02/05/2018

FIR Submit Date: 02/20/2018

FIR Status: \_\_\_\_\_

Inspected Operator Information:

Company Name: HILCORP ENERGY COMPANY

Company Number: 10133

Address: P O BOX 61229

City: HOUSTON State: TX Zip: 77208

LOCATION - Location ID: 333890

Location Name: FLORIDA RIVER ESTATES- Number: 17NESW County: LA PLATA  
N33N9W

Qtrqtr: NESW Sec: 17 Twp: 33N Range: 9W Meridian: N

Latitude: 37.100390 Longitude: -107.851330

FACILITY - API Number: 05-067- -00 Facility ID: 290651

Facility Name: FLORIDA RIVER ESTATES 33 Number: 17-3A  
-9

Qtrqtr: NESW Sec: 17 Twp: 33N Range: 9W Meridian: N

Latitude: 37.100390 Longitude: -107.851330

CORRECTIVE ACTIONS:

1 CA# 114509

Corrective Action: Install, and maintain/replace stormwater controls on both sides of the access road at the entrance to the well pad. Corrective action date is based off of when the inspection was submitted and not the actual inspection date.

Date: 03/31/2018

Response: CA COMPLETED

Date of Completion: 03/08/2018

Operator Comment: Erosion channel has been stablized in order to prevent future erosion. Wattles on the South side of the well pad access entrance were replaced. Storm water management erosion control channel East of the production tanks has been stabilized. Wattles on the East of the well pad near production tanks were replaced. See attached photos.

COGCC Decision: \_\_\_\_\_

COGCC  
Representative: \_\_\_\_\_

**OPERATOR COMMENT AND SUBMITTAL**

Comment: \_\_\_\_\_

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Priscilla Shorty

Signed: \_\_\_\_\_

Title: Operations Reg Tech

Date: 3/9/2018 8:03:25 AM

**ATTACHMENT LIST**

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

**Document Number**

**Description**

401568934

Florida River Estates 33-9 17-3 and 3A Corrective Photos

Total Attach: 1 Files