

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

03/02/2018

Submitted Date:

03/05/2018

Document Number:

688301324**FIELD INSPECTION FORM**Loc ID 317477 Inspector Name: Sherman, Susan On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 68710Name of Operator: PETERSON ENERGY OPERATING INCAddress: 2154 W EISENHOWER BLVDCity: LOVELAND State: CO Zip: 80537**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:5 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
Peterson, Andy	(970) 203-4263	andy.peterson@petersonenergy.com	
Newton, Sarah		sarah@petersonenergyoperating.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
295348	WELL	SI	12/01/2017	OW	121-10985	CHURCH 41B-25	SI

General Comment:

Spill Inspection. Inspection was contacted by the operator at ~5:30 pm on March 1, 2018 about a spill of produced water from the east pit of the Church lease. Landowner and Washington County LGD were also contacted. A Form 19I was in process and no estimate for volume of spill was yet determined. Inspector contacted COGCC NE EPS right after the initial phone call from the operator.

LocationOverall Good: ☐**Signs/Marker:**

Type	BATTERY		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment: 970-669-7411

Corrective Action:

Date: _____

Overall Good: ☐**Spills:**

Type	Area	Volume		
Produced Water		>= 5 bbls		
Comment:	Northern berms of east produced water pit failed releasing produced water into treater and tank battery berms that also failed. Remaining produced water inside tank battery berms and around wellhead was removed with vac truck on the morning of 3/2/2018. Tank battery berms were repaired. See attached photos.			
Corrective Action:	Repair or install berms or other secondary containment devices per Rule 906.d.(1). Completed on 3/1/2018. Recover free liquids and properly dispose in accordance with 907.c. Completed on 3/2/2018. Submit Form 19 to COGCC NE EPS.			Date: 03/06/2018

In Containment: No

Comment: Freeboard on west pit was ~3'.

☐ Multiple Spills and Releases?**Venting:**

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Location Construction

Location ID: 295348 CDP: _____

Comment: _____

Corrective Action: _____ Date: _____

Form 2A COAs:

Comment: No COAs.

Corrective Action: _____ Date: _____

Wildlife BMPs:

Comment: _____

Corrective Action: _____ Date: _____

Comment: _____

Corrective Action: _____ Date: _____

On Site Inspection (305):

Surface Owner Contact Information:

Name: _____ Address: _____

Phone Number: _____ Cell Phone: _____

Operator Rep. Contact Information:

Landman Name: _____ Phone Number: _____

Date Onsite Request Received: _____ Date of Rule 306 Consultation: _____

Request LGD Attendance: _____

LGD Contact Information:

Name: _____ Phone Number: _____ Agreed to Attend: _____

Summary of Landowner Issues:

Summary of Operator Response to Landowner Issues:

Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:

Inspected FacilitiesFacility ID: 295348 Type: WELL API Number: 121-10985 Status: SI Insp. Status: SI**Idle Well**Purpose: ☒ Shut In ☐ Temporarily Abandoned

Reminder: _____

Comment: SI since Dec 2017.

Corrective Action: _____

Date: _____

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401563541	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4393768
688301326	Peterson Church Spill	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4393756