

Inspection Photos

Loc# 309581

Operator: Timber Creek

Inspection Number: 680102780

Inspection Date: 3/7/2018



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources



Photo#1:

Overview of Location to South; note Rill erosion on South Slope indicated by arrow

March 7, 2018



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Timber Creek Loc#309581



Photo#2:
Rill erosion is occurring on Cut Slopes.

March 7, 2018



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Timber Creek Loc#309581



Photo#3:
Rill erosion is occurring on Cut Slope .

March 7, 2018



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Timber Creek Loc#309581



Photo#4:
Sediment is still migrating off Cut Slope.

March 7, 2018



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Timber Creek Loc#309581



Photo#5:

Eroding area of Access Rd that leads up to Terrace on top of Cut Slope on West Side of Site.



Photo#6:

Culvert that needs Maintenance on Access Rd That leads up to Terrace on top of Cut Slope West Side of Site

March 7, 2018



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Timber Creek Loc#309581