



11 has not produced good oil  
in pas - "J"

March 25, 1959

Mr. Byron H. Lord  
P.O. Box 164  
Denver 1, Colorado

Dear Mr. Lord:

Reference is made to our phone conversation of this date regarding your UPRR No. 2 well located SE SW, Section 5, Township 3 South, Range 65 West, and operations in the Second Creek Field.

I have enclosed a copy of our Rules and Regulations and a few of each of the forms that you will be needing, and would like to call your particular attention to Rules 302, 304, 305, 306, 307, 308, 309, 311, and 332 - all of which will probably have some effect on your current operations.

Although you implied that perhaps the UPRR No. 2 well is not completed, if the completion report, OGCC Form 5, cannot be made out at this time, please advise this office by letter of the perforated interval, TD, and any other pertinent information that is currently available.

We appreciate your cooperation in these matters, and if we can be of any assistance at any time, please contact this office.

Very truly yours,

OIL AND GAS CONSERVATION COMMISSION

William R. Smith, Senior Petroleum Engineer

WRS:cm

✓