

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

03/15/2018

Submitted Date:

03/16/2018

Document Number:

679700825**FIELD INSPECTION FORM**
 Loc ID 331872 Inspector Name: ALLISON, RICK On-Site Inspection ☐ 2A Doc Num: _____
Operator Information:OGCC Operator Number: 36200Name of Operator: GRYNBERG* JACK DBA GRYNBERG PETROLEUM COAddress: 3600 S. YOSEMITE ST - STE 900City: DENVER State: CO Zip: 80237-**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**4 Number of Comments2 Number of Corrective Actions☒ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
Grynberg Petroleum		grynpetro@grynberg.com	
Randy Edelen		r.edelen@grynberg.com	
Pesicka, Conor		conor.pesicka@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
267624	WELL	SI	02/11/2015	DSPW	123-21426	CROISSANT 1	SI
454027	SPILL OR RELEASE	AC	02/20/2018		-	Croissant 1	EI

General Comment:

COGCC Environmental Inspection of Spill ID 454027. Corrective Action required from Inspections 684900832 and 690001189 remains in effect.

Inspected FacilitiesFacility ID: 267624 Type: WELL API Number: 123-21426 Status: SI Insp. Status: SI**BradenHead**

Comment: Bradenhead remains below surface. Corrective action noted on previous inspection,
document number: 684903832 & 69000189
Corrective action date remains from original citation.

Corrective Action: Plumb Bradenhead to Surface.

Date: 07/05/2017

Facility ID: 454027 Type: SPILL OR API Number: - Status: AC Insp. Status: EI

Environmental**Spill/Remediation:**

Comment: COGCC Environmental Inspection of spill associated with Croissant 1 well location. Operator discovered vegetation kill at surface. Operator currently investigating spill at Croissant #4 and has not started investigation at this location.

Corrective Action: Comply with COAs on Form 19 Document #401548562 for investigation and remediation of release. Submit all documentation (soil disposal manifests, soil confirmation analytical results, site diagram showing extent of impacts and soil sample locations, and flowline pressure test results) via Form 19 Supplemental Report.

Date: 06/13/2018

Emission Control Burner (ECB): _____

Comment: _____

Pilot: _____ Wildlife Protection Devices (fired vessels): _____

COGCC Comments

Comment	User	Date
Conditions of Approval from Form 19 Document #401548562:	allisonr	03/16/2018
Discrete soil samples must be collected to determine the vertical and horizontal extent of impacts to soil in accordance with Rule 910. Soil samples must be collected from the floor and sidewalls of any excavation and from surface areas impacted by the release. Analyze all soil samples for BTEX, TPH-GRO, TPH-DRO, pH, EC, and SAR.		
Discrete soil samples must be collected to determine the vertical and horizontal extent of impacts to soil in accordance with Rule 910. Soil samples must be collected from the floor and sidewalls of any excavation and from surface areas impacted by the release. Analyze all soil samples for BTEX, TPH-GRO, TPH-DRO, pH, EC, and SAR.		

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401577344	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4405546
679700829	Croissant 1 Inspection Photo 3-15-2018	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4405542