

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

03/20/2018

Submitted Date:

03/20/2018

Document Number:

688500024

FIELD INSPECTION FORM

Loc ID 319709 Inspector Name: CANFIELD, CHRIS On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 10454
Name of Operator: PETROSHARE CORPORATION
Address: 9635 MAROON CIRCLE #400
City: ENGLEWOOD State: CO Zip: 80112

Findings:

- 11 Number of Comments
- 5 Number of Corrective Actions
- Corrective Action Response Requested

Contact Information:

Contact Name	Phone	Email	Comment
Powell, Harold	(918)-774-3120	hpowell@petrosharecorp.com	Field Ops Manager
Brown, Devin	(303)-349-0302	dbrown@petrosharecorp.com	Production Ops Manager
Axelson, John		john.axelson@state.co.us	
MacLaren, Joe		joe.maclaren@state.co.us	
Deranleau, Greg		greg.deranleau@state.co.us	
Lloyd, Bill		blloyd@petrosharecorp.com	Operations Manager

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
319709	LOCATION	AC			-	STATE OF COLORADO AB-62S66W 16NESE	EI

General Comment:

Multiple spoil piles without storm water BMPs.
No signs, no emergency contact info was posted.

Location

Overall Good:

Signs/Marker:

Type	WELLHEAD		
Comment:	Wellhead sign not posted as required by Rule 210.b.		
Corrective Action:	Post sign as required by Rule 210.b.	Date:	04/13/2018

Emergency Contact Number:

Comment:	Emergency contact info not posted as required by Rule 210.b.		
Corrective Action:	Post emergency contact info.	Date:	04/13/2018

Overall Good:

Spills:

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

Venting:

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Location Construction

Location ID: 319709 CDP: _____

Comment: Operator has met the corrective action deadline established in Inspection #68850022 to submit a Form 2A Oil & Gas Location Assessment for prior approval as required by Rule 303.b.

Corrective Action: Operator must submit a Form 2A. The subject tank battery must not be put back into service until a Form 2A has been approved.

Date: 03/12/2018

Form 2A COAs:

Comment: _____

Corrective Action: _____

Date: _____

Wildlife BMPs:

Comment: _____

Corrective Action: _____

Date: _____

Comment: Multiple spoil piles without appropriate storm water BMPs.

Corrective Action: Install storm water BMPs as required by Rule 1002.f.

Date: 03/27/2018

On Site Inspection (305):

Surface Owner Contact Information:

Name: _____ Address: _____

Phone Number: _____ Cell Phone: _____

Operator Rep. Contact Information:

Landman Name: _____ Phone Number: _____

Date Onsite Request Received: _____ Date of Rule 306 Consultation: _____

Request LGD Attendance: _____

LGD Contact Information:

Name: _____ Phone Number: _____ Agreed to Attend: _____

Summary of Landowner Issues:

Summary of Operator Response to Landowner Issues:

Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:

Inspected Facilities

Facility ID: 319709 Type: LOCATION API Number: - Status: AC Insp. Status: EI

Environmental

Spills/Releases:

Type of Spill: _____ Estimated Spill Volume: _____

Comment: Operator has not submitted a Form 19 Supplemental Report as required by Rule 906.b.(1) for Spill/Release Point 453361.

Corrective Action: Submit both a Form 27 Site Investigation & Remediation Work Plan and a Form 19 Supplemental Report for Spill/Release Point 453361. Both submittals were identified as corrective actions in Inspection #688500022. Date: 03/12/2018

Reportable: _____ GPS: Lat _____ Long _____

Proximity to Surface Water: _____ Depth to Ground Water: _____

Water Well Complaint:

Lat _____ Long _____

DWR Receipt Num: _____ Owner Name: _____ GPS : _____

Field Parameters:

Sample Location: _____ Comment: _____

Spill/Remediation:

Comment: Operator removed a partially-buried produced water vessel without prior approval of a Form 27 as required by Rule 905.b.

Corrective Action: Inspection #688500022 required as a corrective action submittal of the above-mentioned Form 27 by 03/12/2018. Date: 03/12/2018

Emission Control Burner (ECB): _____

Comment: _____

Pilot: _____ Wildlife Protection Devices (fired vessels): _____

COGCC Comments

Comment	User	Date
Signs and emergency contact info are not posted. Multiple spoil piles without appropriate storm water BMPs.	canfielc	03/20/2018

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401580816	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4408519
688500025	Photo Log	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4408509