

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

401592117

Date Received:

03/30/2018

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

2 of 2 CAs from the FIR responded to on this Form

2 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10672

Name of Operator: TIMBER CREEK OPERATING LLC

Address: 1001 17TH STREET #1000

City: DENVER State: CO Zip: 80202

Contact Name and Telephone:

Name: _____

Phone: () _____ Fax: () _____

Email: _____

Additional Operator Contact:

Contact Name

Phone

Email

edieftzgerald@tcenergy.us

josephamato@tcenergy.us

COGCC INSPECTION SUMMARY:

FIR Document Number: 680102744

Inspection Date: 03/07/2018

FIR Submit Date: 03/20/2018

FIR Status: _____

Inspected Operator Information:

Company Name: TIMBER CREEK OPERATING LLC

Company Number: 10672

Address: 1001 17TH STREET #1000

City: DENVER State: CO Zip: 80202

LOCATION - Location ID: 307414

Location Name: GOLDEN EAGLE MINE-633S67W Number: 28SWSW County: LAS ANIMAS

Qtrqtr: SWS Sec: 28 Twp: 33S Range: 67W Meridian: 6
W

Latitude: 37.139051 Longitude: -104.899768

FACILITY - API Number: 05-071- -00 Facility ID: 217630

Facility Name: GOLDEN EAGLE MINE Number: V-1

Qtrqtr: SWS Sec: 28 Twp: 33S Range: 67W Meridian: 6
W

Latitude: 37.139051 Longitude: -104.899768

CORRECTIVE ACTIONS:

1 CA# 115029

Corrective Action: Perform Final Reclamation per COGCC 1004 Rules. Establish uniform vegetative cover across entire Location & access road; reclamation activities to be complete by 5/15/18.

Date: 05/15/2018

Response: CA COMPLETED

Date of Completion: 03/29/2018

The ground was scratched to loosen the soil and then treated with 4-6-4 Sustane fertilizer, AM 120 soil enhancer

Operator Comment: and Flexterra High Performance Flexible Growth Medium to promote the establishment of vegetation.

COGCC Decision: _____

COGCC Representative: _____

2 CA# 115030

Corrective Action: Install or repair required BMPs per Rule 1002.f. CA date reflects need for stormwater controls to be in place due to imminent arrival of precipitation season.

Date: 04/03/2018

Response: CA COMPLETED

Date of Completion: 03/29/2018

Operator Comment: The (2) slope breakers were swelled out to avoid a "V" shaped channel. Rip rap was placed in the ditch line to stabilize the soil and provide long term erosion control.

COGCC Decision: _____

COGCC Representative: _____

OPERATOR COMMENT AND SUBMITTAL

Comment: All corrective actions have been addressed for this location. See attached photos for details

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Edie Fitzgerald

Signed: _____

Title: SR Environmental Tech.

Date: 3/30/2018 9:41:13 AM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
401592185	Erosion control BMP's installed along the slope breaker. Reseeded the bare areas of the location.

Total Attach: 1 Files