

FORM
6
Rev
12/05

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203 Phone: (303) 894-2100 Fax: (303) 894-2109



| | | | |
|-------------------------------|----|----|----|
| DE | ET | OE | ES |
| Document Number: 401602001 | | | |
| Date Received: | | | |

WELL ABANDONMENT REPORT

This form is to be submitted as an Intent to Abandon whenever an abandonment is planned on a borehole. After the abandonment is complete, this form shall again be submitted as a Subsequent Report of the actual work completed. The approved intent shall be valid for six months after the approval date, after that period, a new intent will be required. Attachments required with the Intent to Abandon are wellbore diagrams of the current configuration and the proposed configuration with plugs set. A Subsequent Report of Abandonment shall indicate the actual work completed. Attachments required with a Subsequent Report are a wellbore diagram showing plugs that were set and casing remaining in the hole, the job summaries from all plugging contractors used, including wireline and cementing (third party verification) and any logs that may have been run during abandonment.

| | |
|---|-------------------------------------|
| OGCC Operator Number: <u>72118</u> | Contact Name: <u>Tom Roelfs</u> |
| Name of Operator: <u>PRIME OPERATING COMPANY</u> | Phone: <u>(970) 324-1686</u> |
| Address: <u>9821 KATY FREEWAY STE 1050</u> | Fax: _____ |
| City: <u>HOUSTON</u> State: <u>TX</u> Zip: <u>77042</u> | Email: <u>tr_services@yahoo.com</u> |

For "Intent" 24 hour notice required, Name: _____ Tel: _____
 COGCC contact: Email: _____

| | |
|---|--|
| API Number: <u>05-125-06706-00</u> | Well Number: <u>6-18</u> |
| Well Name: <u>WEYERMAN</u> | |
| Location: QtrQtr: <u>SENW</u> Section: <u>18</u> Township: <u>5S</u> Range: <u>43W</u> Meridian: <u>6</u> | |
| County: <u>YUMA</u> | Federal, Indian or State Lease Number: _____ |
| Field Name: <u>BONNY</u> | Field Number: <u>7325</u> |

Notice of Intent to Abandon Subsequent Report of Abandonment

Only Complete the Following Background Information for Intent to Abandon

Latitude: 39.626319 Longitude: -102.224300

GPS Data:
 Date of Measurement: 09/11/2011 PDOP Reading: 3.5 GPS Instrument Operator's Name: J Roelfs

Reason for Abandonment: Dry Production Sub-economic Mechanical Problems
 Other _____

Casing to be pulled: Yes No Estimated Depth: _____

Fish in Hole: Yes No If yes, explain details below

Wellbore has Uncemented Casing leaks: Yes No If yes, explain details below

Details: _____

Current and Previously Abandoned Zones

| Formation | Perf. Top | Perf. Btm | Abandoned Date | Method of Isolation | Plug Depth |
|------------------|-----------|-----------|----------------|---------------------|------------|
| NIOBRARA | 1470 | 1490 | | | |
| Total: 1 zone(s) | | | | | |

Casing History

| Casing Type | Size of Hole | Size of Casing | Weight Per Foot | Setting Depth | Sacks Cement | Cement Bot | Cement Top | Status |
|-------------|--------------|----------------|-----------------|---------------|--------------|------------|------------|--------|
| SURF | 9+7/8 | 7 | 17 | 281 | 85 | 281 | 0 | VISU |
| 1ST | 6+1/4 | 4+1/2 | 10.5 | 1,645 | 150 | 1,645 | 800 | CBL |

Plugging Procedure for Intent and Subsequent Report

CIBP #1: Depth 1415 with 2 sacks cmt on top. CIBP #2: Depth 340 with 26 sacks cmt on top.
 CIBP #3: Depth _____ with _____ sacks cmt on top. CIBP #4: Depth _____ with _____ sacks cmt on top.
 CIBP #5: Depth _____ with _____ sacks cmt on top.

NOTE: Two(2) sacks cement required on all CIBPs.

Set 26 sks cmt from 330 ft. to _____ ft. Plug Type: CASING Plug Tagged:
 Set 35 sks cmt from 330 ft. to _____ ft. Plug Type: ANNULUS Plug Tagged:
 Set _____ sks cmt from _____ ft. to _____ ft. Plug Type: _____ Plug Tagged:
 Set _____ sks cmt from _____ ft. to _____ ft. Plug Type: _____ Plug Tagged:
 Set _____ sks cmt from _____ ft. to _____ ft. Plug Type: _____ Plug Tagged:

Perforate and squeeze at 330 ft. with 38 sacks. Leave at least 100 ft. in casing _____ CICR Depth
 Perforate and squeeze at _____ ft. with _____ sacks. Leave at least 100 ft. in casing _____ CICR Depth
 Perforate and squeeze at _____ ft. with _____ sacks. Leave at least 100 ft. in casing _____ CICR Depth
(Cast Iron Cement Retainer Depth)

Set _____ sacks half in. half out surface casing from _____ ft. to _____ ft. Plug Tagged:
 Set _____ sacks at surface
 Cut four feet below ground level, weld on plate Above Ground Dry-Hole Marker: Yes No
 Set _____ sacks in rat hole Set _____ sacks in mouse hole

Additional Plugging Information for Subsequent Report Only

Casing Recovered: _____ ft. _____ inch casing Plugging Date: 04/07/2018
 of _____
 *Wireline Contractor: Peak Wireline Services, Inc. *Cementing Contractor: Basic Energy Services
 Type of Cement and Additives Used: Class G Cement
 Flowline/Pipeline has been abandoned per Rule 1103 Yes No *ATTACH JOB SUMMARY

Technical Detail/Comments:

I hereby certify all statements made in this form are, to the best of my knowledge, true, correct, and complete.

Signed: _____ Print Name: Tom Roelfs
 Title: Foreman Date: _____ Email: TR_SERVICES@YAHOO.COM

Based on the information provided herein, this Well Abandonment Report (Form 6) complies with COGCC Rules and applicable orders and is hereby approved.

COGCC Approved: _____ Date: _____

CONDITIONS OF APPROVAL, IF ANY:

| COA Type | Description |
|----------|-------------|
| | |

Attachment Check List

| <u>Att Doc Num</u> | <u>Name</u> |
|--------------------|--------------------------------------|
| 401602037 | CEMENT JOB SUMMARY |
| 401602039 | WIRELINE JOB SUMMARY |
| 401602042 | WELL ABANDONMENT REPORT (SUBSEQUENT) |

Total Attach: 3 Files

General Comments

| <u>User Group</u> | <u>Comment</u> | <u>Comment Date</u> |
|-------------------|----------------|------------------------|
| | | Stamp Upon Approval |

Total: 0 comment(s)