

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

401576237

Date Received:

04/06/2018

Spill report taken by:

NEIDEL, KRIS

Spill/Release Point ID:

439715

SPILL/RELEASE REPORT (SUPPLEMENTAL)

This form is to be submitted by the party responsible for the oil and gas spill or release. Refer to COGCC Rule 906.b. for reporting requirements of spills or releases of E&P Waste or produced fluids. Submit a Site Investigation and Remediation Workplan (Form 27) when requested by the Director.

OPERATOR INFORMATION

Name of Operator: CHEVRON USA INC	Operator No: 16700	Phone Numbers Phone: (970) 675-3814 Mobile: (970) 697-8385 Email: mhaub@chevron.com
Address: 100 CHEVRON RD		
City: RANGELY	State: CO Zip: 81648	
Contact Person: Michael Haub		

INITIAL SPILL/RELEASE REPORT

Initial Spill/Release Report Doc# 400722520

Initial Report Date: 11/03/2014 Date of Discovery: 10/31/2014 Spill Type: Recent Spill

Spill/Release Point Location:

Location of Spill/Release: QTRQTR SESE SEC 26 TWP 2N RNG 103W MERIDIAN 6

Latitude: 40.108880 Longitude: -108.916800

Municipality (if within municipal boundaries): County: RIO BLANCO

Reference Location:

Facility Type: FLOWLINE ☐ Facility/Location ID No ☐
☐ No Existing Facility or Location ID No.
☒ Well API No. (Only if the reference facility is well) 05-103-05677

Fluid(s) Spilled/Released (please answer Yes/No):

Was one (1) barrel or more spilled outside of berms or secondary containment? Yes

Secondary containment, **including walls & floor regardless of construction material**, must be sufficiently impervious to contain any discharge from primary containment until cleanup occurs.

Were Five (5) barrels or more spilled? No

Estimated Total Spill Volume: use same ranges as others for values

Estimated Oil Spill Volume(bbl): 0 Estimated Condensate Spill Volume(bbl): 0

Estimated Flow Back Fluid Spill Volume(bbl): 0 Estimated Produced Water Spill Volume(bbl): >=1 and <5

Estimated Other E&P Waste Spill Volume(bbl): 0 Estimated Drilling Fluid Spill Volume(bbl): 0

Specify:

Land Use:

Current Land Use: NON-CROP LAND Other(Specify):

Weather Condition: 30 degrees and sunny

Surface Owner: OTHER (SPECIFY) Other(Specify): Whiting Surface

Check if impacted or threatened by spill/Release (please answer Yes/No to all that apply):

Waters of the State ☐ Residence/Occupied Structure ☐ Livestock ☐ Public Byway ☐ Surface Water Supply Area ☐

As defined in COGCC 100-Series Rules

Describe what is known about the spill/release event (what happened -- including how it was stopped, contained, and recovered):

Friday (10-31-2014) at approximately 8:00 a leak occurred on a 3" coated spool on the injection line from Emerald 17 (40.10888,-108.9168). Approximately 2.5 BBLs of produced water was released. The lateral valve was shut in immediately upon detection. Vacuum truck recovered an estimated 2 BBLs. All of the fluids were contained in the RWSU field. No impact to surface water. The affected area has been water washed and soil samples will be taken.

List Agencies and Other Parties Notified:

OTHER NOTIFICATIONS

Date	Agency/Party	Contact	Phone	Response
10/31/2014	COGCC	Kris Neidel	303-871-1963	Sent Email
10/31/2014	Rio Blanco	Mark Sprague	970-878-9584	Sent Email
10/31/2014	Chevron Land Representative	Shalyce Holmes	432-687-7348	Sent Email

SPILL/RELEASE DETAIL REPORTS

#1	Supplemental Report Date: 04/06/2018		
FLUIDS	BBL's SPILLED	BBL's RECOVERED	Unknown
OIL	0	0	<input type="checkbox"/>
CONDENSATE	0	0	<input type="checkbox"/>
PRODUCED WATER	2	2	<input type="checkbox"/>
DRILLING FLUID	0	0	<input type="checkbox"/>
FLOW BACK FLUID	0	0	<input type="checkbox"/>
OTHER E&P WASTE	0	80	<input type="checkbox"/>

specify: freshwater wash

Was spill/release completely contained within berms or secondary containment? NO Was an Emergency Pit constructed? NO

*Secondary containment, **including walls & floor regardless of construction material**, must be sufficiently impervious to contain any discharge from primary containment until cleanup occurs.*

A Form 15 Pit Report shall be submitted within 30 calendar days after the construction of an emergency pit

Impacted Media (Check all that apply) ☒ Soil ☐ Groundwater ☐ Surface Water ☐ Dry Drainage Feature

Surface Area Impacted: Length of Impact (feet): 178 Width of Impact (feet): 4

Depth of Impact (feet BGS): 0 Depth of Impact (inches BGS): _____

How was extent determined?

Chevron Spill calculation sheet generated by operator on site at time of spill

Soil/Geology Description:

high clay

Depth to Groundwater (feet BGS) 3320 Number Water Wells within 1/2 mile radius: 0

If less than 1 mile, distance in feet to nearest

Water Well	<u>3868</u>	None <input type="checkbox"/>	Surface Water	None <input checked="" type="checkbox"/>
Wetlands	_____	None <input checked="" type="checkbox"/>	Springs	None <input checked="" type="checkbox"/>
Livestock	_____	None <input checked="" type="checkbox"/>	Occupied Building	None <input checked="" type="checkbox"/>

Additional Spill Details Not Provided Above:

REQUEST FOR CLOSURE

Spill/Release Reports should be closed when impacts have been remediated or when further investigation and corrective actions will take place under an approved Form 27.

Basis for Closure: ☒ Corrective Actions Completed (documentation attached)

☐ Work proceeding under an approved Form 27

Form 27 Remediation Project No: _____

OPERATOR COMMENTS:

Please Find attached the soil samples showing compliance with Table 910-1.
Closure Requested.

I hereby certify all statements made in this form are to the best of my knowledge true, correct, and complete.

Signed: _____ Print Name: Michael Haub

Title: HES Specialist Date: 04/06/2018 Email: mhaub@chevron.com

COA Type

Description

--	--

Attachment Check List

Att Doc Num

Name

401576237	SPILL/RELEASE REPORT(SUPPLEMENTAL)
401576244	ANALYTICAL RESULTS
401599157	AERIAL PHOTOGRAPH
401611546	FORM 19 SUBMITTED

Total Attach: 4 Files

General Comments

User Group

Comment

Comment Date

Agency	Based on review of information presented it appears that no further action is necessary at this time, and COGCC approves the closure request. However, should future conditions at the site indicate contaminant concentrations in soils exceeding COGCC standards or if ground water is found to be significantly impacted, then further investigation and/or remediation activities may be required at the site.	03/21/2018
--------	--	------------

Total: 1 comment(s)