

FORM
6Rev
12/05

State of Colorado Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203 Phone: (303) 894-2100 Fax: (303) 894-2109



DE	ET	OE	ES
----	----	----	----

Document Number:

401627152

Date Received:

WELL ABANDONMENT REPORT

This form is to be submitted as an Intent to Abandon whenever an abandonment is planned on a borehole. After the abandonment is complete, this form shall again be submitted as a Subsequent Report of the actual work completed. The approved intent shall be valid for six months after the approval date, after that period, a new intent will be required. Attachments required with the Intent to Abandon are wellbore diagrams of the current configuration and the proposed configuration with plugs set.

A Subsequent Report of Abandonment shall indicate the actual work completed. Attachments required with a Subsequent Report are a wellbore diagram showing plugs that were set and casing remaining in the hole, the job summaries from all plugging contractors used, including wireline and cementing (third party verification) and any logs that may have been run during abandonment.

OGCC Operator Number: 69175

Contact Name: Jenifer Hakkarinen

Name of Operator: PDC ENERGY INC

Phone: (303) 8605800

Address: 1775 SHERMAN STREET - STE 3000

Fax:

City: DENVER State: CO Zip: 80203

Email: Jenifer.Hakkarinen@pdce.com

For "Intent" 24 hour notice required,

Name:

Tel:

COGCC contact:

Email:

API Number 05-123-20659-00

Well Name: FICKEL

Well Number: 41-21

Location: QtrQtr: NENE Section: 21 Township: 4N Range: 67W Meridian: 6

County: WELD

Federal, Indian or State Lease Number:

Field Name: WATTENBERG

Field Number: 90750

☐ Notice of Intent to Abandon☒ Subsequent Report of Abandonment

Only Complete the Following Background Information for Intent to Abandon

Latitude: 40.304140

Longitude: -104.888110

GPS Data:

Date of Measurement: 07/15/2010

PDOP Reading: 1.6

GPS Instrument Operator's Name: Holly L. Tracy

Reason for Abandonment:

☐ Dry☐ Production Sub-economic☐ Mechanical Problems☐ Other

Casing to be pulled:

☐ Yes☐ No

Estimated Depth:

Fish in Hole:

☐ Yes☐ No

If yes, explain details below

Wellbore has Uncemented Casing leaks:

☐ Yes☐ No

If yes, explain details below

Details:

Current and Previously Abandoned Zones

Formation	Perf. Top	Perf. Btm	Abandoned Date	Method of Isolation	Plug Depth
CODELL	7275	7285	03/30/2018	B PLUG CEMENT TOP	7225

Total: 1 zone(s)

Casing History

Casing Type	Size of Hole	Size of Casing	Weight Per Foot	Setting Depth	Sacks Cement	Cement Bot	Cement Top	Status
SURF	12+1/4	8+5/8	24	401	280	401	0	VISU
1ST	7+7/8	4+1/2	10.5	7,441	200	7,441	6,440	CBL

Plugging Procedure for Intent and Subsequent Report

CIBP #1: Depth 7225 with 2 sacks cmt on top. CIBP #2: Depth 6905 with 2 sacks cmt on top.
CIBP #3: Depth _____ with _____ sacks cmt on top. CIBP #4: Depth _____ with _____ sacks cmt on top.
CIBP #5: Depth _____ with _____ sacks cmt on top.

NOTE: Two(2) sacks cement required on all CIBPs.

Set 160 sks cmt from 1725 ft. to 1280 ft. Plug Type: STUB PLUG Plug Tagged: ☐
Set 264 sks cmt from 653 ft. to 0 ft. Plug Type: OPEN HOLE Plug Tagged: ☐
Set _____ sks cmt from _____ ft. to _____ ft. Plug Type: _____ Plug Tagged: ☐
Set _____ sks cmt from _____ ft. to _____ ft. Plug Type: _____ Plug Tagged: ☐
Set _____ sks cmt from _____ ft. to _____ ft. Plug Type: _____ Plug Tagged: ☐

Perforate and squeeze at 4950 ft. with 200 sacks. Leave at least 100 ft. in casing 4565 CICR Depth

Perforate and squeeze at _____ ft. with _____ sacks. Leave at least 100 ft. in casing _____ CICR Depth

Perforate and squeeze at _____ ft. with _____ sacks. Leave at least 100 ft. in casing _____ CICR Depth

(Cast Iron Cement Retainer Depth)

Set _____ sacks half in. half out surface casing from _____ ft. to _____ ft. Plug Tagged: ☐

Set _____ sacks at surface

Cut four feet below ground level, weld on plate Above Ground Dry-Hole Marker: ☐ Yes ☐ No

Set _____ sacks in rat hole Set _____ sacks in mouse hole

Additional Plugging Information for Subsequent Report Only

Casing Recovered: 1600 ft. of 4+1/2 inch casing Plugging Date: 03/30/2018

*Wireline Contractor: Ranger

*Cementing Contractor: C&J

Type of Cement and Additives Used: 15.8 PPG CL G NEAT + 2% CaCl

Flowline/Pipeline has been abandoned per Rule 1103 ☐ Yes ☐ No

*ATTACH JOB SUMMARY

Technical Detail/Comments:

Fickel 41-21 (05-123-20659)/Plugging Procedure
Producing Formation (Perforations): Codell: 7275'-7285'
TD: 7480' PBD: 7429'
Surface Casing: 8 5/8" 24# @ 401' w/ 280 sxs
Production Casing: 4 1/2" 10.5# @ 7441' w/ 200 sxs cmt (TOC @ 6440' - CBL).

Tubing: 2 3/8" tubing set @ 7266' (4/4/2002).

Procedure:

1. MIRU pulling unit. Pull 2 3/8" tubing.
2. RU wireline company.
3. TIH with CIBP. Set BP at 7225'. Top with 2 sxs 15.8#/gal CI G cement.
4. TIH with CIBP. Set BP at 6905'. Top with 2 sxs 15.8#/gal CI G cement.
5. Shoot lower squeeze holes at 4950'. Shoot upper squeeze holes at 4550'.
6. Set CICR at 4565'. Sting in and pump 190 sxs 15.8#/gal CI G cement. Sting out and pump 10 sxs on top of CICR.
7. TIH with casing cutter. Cut 4 1/2" casing at 1600'. Pull cut casing.
8. TIH with tubing to 1725'. RU cementing company. Mix and pump 160 sxs 15.8#/gal CI G + 2% CaCl cement down tubing to 1280'.
9. TIH with tubing to 653'. RU cementing company. Mix and pump 264 sxs 15.8#/gal CI G + 2% CaCl cement down tubing. Cement circulate to surface.
10. Cut surface casing 6' below ground level and weld on cap.

I hereby certify all statements made in this form are, to the best of my knowledge, true, correct, and complete.

Signed: _____

Print Name: Jenifer Hakkarinen

Title: Reg TECh

Date: _____

Email: Jenifer.Hakkarinen@pdce.com

Based on the information provided herein, this Well Abandonment Report (Form 6) complies with COGCC Rules and applicable orders and is hereby approved.

COGCC Approved: _____

Date: _____

CONDITIONS OF APPROVAL, IF ANY:

COA Type

Description

--	--

Attachment Check List

Att Doc Num

Name

401627207	CEMENT JOB SUMMARY
401627215	WELLBORE DIAGRAM

Total Attach: 2 Files

General Comments

User Group

Comment

Comment Date

		Stamp Upon Approval
--	--	---------------------

Total: 0 comment(s)