

Eck 12-90-1 #1 Corrective Actions Addressed in Nov/Dec 2017



Photo 1. Installation of an additional Diversion Ditch above the Cut Slope as recommended by COGCC.



Photo 2. Deepening of on-pad Diversion Ditch to prepare for Jute Matting Installation in Spring 2018.

Eck 12-90-1 #1 Corrective Actions Addressed in Nov/Dec 2017



Photo 3. Deepening of on-pad Diversion Ditch to prepare for installation of Jute Matting in Spring 2018.