

LOPEZ CANYON SWD 1 API# 05-071-09733 – TIMBER CREEK
OGCC OPERATOR NUMBER 10672 – INSPECTION DATE: MAY 07, 2018
CORRECTIVE ACTIONS COMPLETED REGARDING COGCC FIR DOCUMENT # 680102780



PHOTO 1: OVERVIEW OF LOCATION TO SOUTH. GRADING TECHNIQUES WERE INSTALLED ON THE CONTOUR TO ELIMINATE THE RILL FORMATION ON THE CUT SLOPE. THE EARTH DISTURBANCE WAS STABILIZED BY HYDRO-SEEDING USING AN APPROVED HILL RANCH SEED MIX TO PROMOTE THE ESTABLISHMENT OF VEGETATION.

LOPEZ CANYON SWD 1 API# 05-071-09733 – TIMBER CREEK
OGCC OPERATOR NUMBER 10672 – INSPECTION DATE: MAY 07, 2018
CORRECTIVE ACTIONS COMPLETED REGARDING COGCC FIR DOCUMENT # 680102780



PHOTO 2: CLOSE UP PHOTO OF CUT SLOPE SOIL CONDITIONS.

LOPEZ CANYON SWD 1 API# 05-071-09733 – TIMBER CREEK
OGCC OPERATOR NUMBER 10672 – INSPECTION DATE: MAY 07, 2018
CORRECTIVE ACTIONS COMPLETED REGARDING COGCC FIR DOCUMENT # 680102780



PHOTO 3: CLOSE UP PHOTO OF CUT SLOPE SOIL CONDITIONS WHERE MOLES ARE DISTURBING THE SOIL.

LOPEZ CANYON SWD 1 API# 05-071-09733 – TIMBER CREEK
OGCC OPERATOR NUMBER 10672 – INSPECTION DATE: MAY 07, 2018
CORRECTIVE ACTIONS COMPLETED REGARDING COGCC FIR DOCUMENT # 680102780



PHOTO 4: GRADING TECHNIQUES WHERE INSTALLED TO REMOVE RILL FORMATION.

LOPEZ CANYON SWD 1 API# 05-071-09733 – TIMBER CREEK
OGCC OPERATOR NUMBER 10672 – INSPECTION DATE: MAY 07, 2018
CORRECTIVE ACTIONS COMPLETED REGARDING COGCC FIR DOCUMENT # 680102780



PHOTO 5: GRADING TECHNIQUES WERE INSTALLED ON THE CONTOUR TO CORRECT RILL FORMATION. THE EARTH DISTURBANCE WAS STABILIZED BY HYDRO-SEEDING USING AN APPROVED HILL RANCH SEED MIX TO PROMOTE THE ESTABLISHMENT OF VEGETATION.

LOPEZ CANYON SWD 1 API# 05-071-09733 – TIMBER CREEK
OGCC OPERATOR NUMBER 10672 – INSPECTION DATE: MAY 07, 2018
CORRECTIVE ACTIONS COMPLETED REGARDING COGCC FIR DOCUMENT # 680102780



PHOTO 6: RIP RAP WAS PLACED IN THE PORTION OF THE TERRACED SLOPE THAT WAS ERODING TO CONTROL THE EROSION.

LOPEZ CANYON SWD 1 API# 05-071-09733 – TIMBER CREEK
OGCC OPERATOR NUMBER 10672 – INSPECTION DATE: MAY 07, 2018
CORRECTIVE ACTIONS COMPLETED REGARDING COGCC FIR DOCUMENT # 680102780



PHOTO 7: THE LOOSE SOIL WAS REMOVED FROM THE CULVERT OUTLET.